## UNCLASSIFIED

# AD NUMBER AD890905 LIMITATION CHANGES TO: Approved for public release; distribution is unlimited. FROM: Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; 22 OCT 1971. Other requests shall be referred to Naval Ordnance Laboratory, Attn: Code 233, White Oak, MD 20910. **AUTHORITY** USNSWC ltr dtd 4 Dec 1974

THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEASE UNDER DGD DIRECTIVE 5200.20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED,



NOLTR 71-124

D EVELOPMENT AND TEST OF THERMAL PROTECTION METHODS FOR BOMB FUZES TO EXTEND COOK-OFF TIME IN LARGE AIRCRAFT FUEL FIRES

AD NO. GDC FILE COPY

By Donald Levine

9 DECEMBER 1971



NAVAL ORDNANCE LABORATORY, WHITE OAK, SILVER SPRING, MARYLAND

20.910

NOLTR 71-124

DISTRIBUTION LIMITED TO U.S. GOVERNMENT AGENCIES ONLY: Test and Evaluation ——

DATE STATEMENT APPLIED: 10/22/71

OTHER REQUESTS FOR THIS PUBLICATION MUST BE REFERRED TO: NOL CODE 2.33


215

CESSION SW	WHITE BESTION [
MT:	BUFF SESTION D
DC	
MANAGENCED	
ustification	
64	N/AVRICABILITY COURS
BIST2124110	N/AVRICABILITY COURS
aist.	AVAIL and or SPECIA
	1
	1
1121	1

•

WRITE SERTION []

# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

DEVELOPMENT AND TEST OF THERMAL PROTECTION METHODS FOR BOMB FUZES TO EXTEND COOK-OFF TIME IN LARGE AIRCRAFT FUEL FIRES

Prepared by: Donald Levine

ABSTRACT: (U) Both experimental and theoretical investigations have been performed on ways of extending the cook-off times of the Noze Fuze M904E2 and M14E Adapter Booster when engulfed in a liquid hydrocarbon fire. Several insulative materials were examined for utilization in fuzes and adapter booster fixes. The materials showing the greatest promise when fabricated into sleeves, were Candidates No. 10 and No. 14. These materials extended the cook-off times of the Fuze M904E2 with deflagration being the usual reaction. An open Adapter Booster problem was determined to exist. Shen the Adapter Booster was unprotected and flame was directed into the open cavity, cook-off resulted in approximately four minutes. When the Adapter Booster was protected with intumescent paint on the adapter ring, and a disc and washer of Candidate No. 10 was inserted into the booster cavity, times in excess of 12 minutes were obtained. When the two fixes were combined the times to cook-off, with a somewhat lower fire temperature, were in excess of 12 minutes with detonation being the reaction. This report describes the cook-off test procedures and discusses the laboratory and field results of cook-off fixes for Fuze M904E2 and M145 Adapter Booster.

Approved by:

A. B. DIETEMANN, Chief Chemical Engineering Division Chemistry Research Department U. S. NAVAL ORDNANCE LABORATORY WHITE OAK, MARYLAND

> 1 UNCLASSIFIED

#### UNCLASSIFIED

NOITE 71-124

9 December 1971

Development and Test of Thermal Frotection Methods for Bomb Fuzes to Extend Cook-off Time in Large Aircraft Fuel Fires

(U) NOLTR 69-112 and NOLTR 71-54 are previous reports that describe the cook-off characteristics of ordnance items when engulfed in a liquid hydrocarbon fuel fire. This report describes the results of a number of experimental and analytical investigations, supported by Task NOL-346/NMC Prob. No. 5, to extend the cook-off time of the Nose Fuze M904E2 and the M148 (T45E7) Adapter Booster. Based on an elimination process two (2) fixes for the M904E2 Fuze and one (1) fix for the M148 Adapter Booster were procured for evaluation. The recommendation for release to production of the chosen fix is contained in reference (4).

ROBERT WILLIAMSON II

ALBERT LIGHTBODY

By direction

## CONTENTS

	1 177
INTRODUTION	۲.,
THEORY	1
MATERIAL CONSIDERATION	
Specimen Preparation and Fire Tests at NOL	
FIELD TEST PROGRAM	
FAST COOK-OFF TEUT ARRANGEMENT	
INSTRUMENTATION	
HARDWARE DESCRIPTION	
GENERAL PURPOSE 500-POUND MARK '2 POSE	** .*
DEFINITION OF TERMS	/
EXPERIMENTAL RESULTS AND CONCLUSIONS	••
Fuze Test No. 1 through Fuze Test No. 2;	5.1-1
OPEN ADAPTER BOOSTER INVESTIGATIONS	72
SUMMARY AND CONCLUSIONS	17.
AJKHOWLEDGEMENT	1:5
REFERENCES  APPENDIX A  APPENDIX B  APPENDIX C  APPENDIX D	1:5 A-1 B-1 C-1 D-1
Figure Title	Fage
Foam Insulation Thickness Needed for Fuse Protection for 10 Minutes	•
at 1750°F	10

111 UNCLASSIFIED

Figure	Title	Page
6	Shore A Durometer Hardness vs Time for these	
	Temperatures	25
7	Shore A Durometer Hardness vs Time for these	• *
•	Temperatures Exposures	26
ځ	Shore A Durometer Hardness vs Time for these	
Ũ	Temperatures Exposures	27
y	Shore A Durometer Hardness vs Time for these	<b>•</b> {
2	Temperatures Exposures	29
10	Shore A Durometer Hardness vs Time for these	23
10	Morrowstuned Exposures	30
11	Temperatures Exposures	30
11	Shore A Durometer Hardness vs Time for these	~ =
	Temperatures Exposures	31
12	Shore A Durometer Hardness vs Time for these	•
_ =	Temperatures Exposures	32
13	Shore A Durometer Hardness vs Time for these	
	Temperatures Exposures	33
14	Shore A Durometer Hardness vs Time for these	
	Temperatures Exposures	34
15a	Schematic of Field Test Arrangement	34 37 340
15b	Test Site Layout	38
16	The FM Recording System	40
17	M904E2 Installed in a Mark 80 Series Bomb	42
18	Mechanical Nose Fuze M904E2 - Sectional and	
	Exploded Views	43
19	Adapter Booster T45E Series	44
20	Mechanical Ling Delay Fuze Mark 346 Mod 0	45
21a	Fuze Drive Mark 5 Mod 1	45
21b	Typical Arming Assembly	45
22	Adapter Booster T46 Series	46
23	Mk 82 General Purpose Bomb	48
24	Photograph of Thermally Protected Live Mk 82 Bomb	, ,
	Outfitted with Mk 346 Tail Fuze and M904E2 Nose	
	Fuze	50
25	Ionization Probe Location in Mk 82 Thermally	٥
رے	Protected Bomb	51
26	Representative Case Fragment from Test Fuze No. 1.	53
27	Top View of Thermally Protected Live Mk 82 Bomb	ت ر
21	Containing Mk 346 Tail Fuze and M904E2 Nose Fuze -	
	Figs. Chat Ma 0	54
00	Fuze Shot No. 2	24
<b>2</b> 8	Cratering and Case Remnants of Fuze Test No. 2	54
29	Actual Air Blast Trace of Fuze Test No. 2	55
30	Bomb Fragments from Fuze Test No. 3. Top View	
	Shows Tail Section. Bottom View Shows Aft End of	
	Bomb	56
31	Air Blast Curve of Fuze Test No. 3	58
32	Thermocouple Arrangement in M14c (T45E7) Adapter	
	Booster	60
<b>3</b> 3	Thermocouple Arrangement in Nose Fuze M904E2	61
34	Time Temperature Plot of Fuze Test No. 4	62
33 34 35	Time Temperature Plot of Fuze Test No. 5	64
36	Time Temperature Plot of Fuze Test No. 6	65

Figure	11:10	Fare
31	Time Temperature Flot of Fuse Test No. 7	
30	Thermocouple Location in Auapter booster Well -	
	Fuze Test No. C	بز
45	Time Temperature Plot of Pure Test No	1
	Test Set Up for Fuze Test No. 4	
41	Time Temperature Plot of Fuze Test No. :	-
42	Time Temperature Plot of Fuz. Test No. 1c	
43	Typical Arrangement of Aircraft on Flight Deck	76
44	Photograph of Test Set Up of Puze Test No. 11	i C
45	Photograph of Test Site After Fuze Test No. 11	
40	Time Temperature Plot of Fuze Test No. 11	1 -
47	Test Set Up Before Test No. 12	 : 1
45	Test Set Up After Fuze Test No. 12	
4 =	Time Temperature Plot of Fuse Test No. 12	
50	Time Temperature Plot of Fuze Test No. 15 Time Temperature Plot of Fuze Test No. 14	7 7
51 50		
) č	Wind Generator	
52 53 54 55	Air Flow Patterns for 300 H.P. Wind Generator	- 1
44ر د د د	Experimental Thermocouple Grid for Determining	
ンノ	Hottest Point in Fire	٠,٠
56	Time Temperature Curve of Thermocouple Positioned	*
	One Foot Above Fuel Level	34
57	Time Temperature Curve of Thermocouple Positioned	- 1
<i>J</i> !	Two Feet Above Fuel Level	50
58	Time Temperature Curve of Thermocouple Positioned	
,-	Three Feet Above Fuel Level	51
59	Time Temperature Curve of Thermocouple Positioned	
	Four Feet Above Fuel Level	_ 1
60	Time Temperature Curve of Thermocouple Positioned	
	Five Feet Above Fuel Level	
61	Parts Arrangement of M148 Adapter Booster Modified	
	to Incorporate Intumescent Paint Fix	1
62	Test Configuration for Fuze Test No. 15	3-5
63	Time Temperature Curve for Fuze Test No. 15	
64	Time Temperature Curve for Fuze Test No. 15	30
65	Profile of Fire Temperature for Fuze Test No. 15.	97
66	Disc and Washer Made from Candidate No. 10 Material	100
67	Photograph of Area After Fuze Test No. 16	
68	Fire Temperature Thermogram of Fuze Test No. 16	101
69	M148 Adapter Booster Thermogram of Fuze Test No. 16	101
70	M148 Adapter Booster Thermogram of Fuze Test No. 16	102
71	Mold No. 1 for Protective Fuze Covering	106
72	Mold No. 2 for Protective Fuze Covering	107
73 74	Jig for Drilling Holes in Protective Covering	105
74	Photograph of Test Set Up for Fuze Test No. 18	110
75	Thermograms of Fuze Thermocouples for Fuze Test	111
76	No. 18 Thermograms of Adapter Booster Thermocouples for	111
100	Fuze Test No. 15	112
	TAND FORM IN A THIRD SECTION OF THE	4 4 6-

Figure	Fitle	Page
17	Thermogram of Thermocomples for Fuze Test No. 19	114
7	Thermograms of Adapter Booster Thermocouples for	
	Shot No. 19	115
7	Schematic of Candidate No. 1, N . 1 . No. 5 and No.	
	14 Sleeve Photograph of Sleeve Candidate No. 1, No. 5	116
40		
	Modified No. 10, No. $1^k$	117
<b>:1</b>	Thermogram of Fuse Test No. 3 with Candidate No.	
	; Sleeve	11c
ore to	Therm gram of Fulle Test No. 16 with Candidate No. 1	
	Gleeve and Adapter bootter washer	11:
	Thermogram of Puse Test No. 20 with Candidate No.	
. 1	14 Sleeve Thermogram of Fuse Test No. 1 with Candidate No. 10	11.
- L	Thermogram of Fude Pett No. With Candidate No. 10	11.
25	Thermogram of Adapter Booster Thermocouple in Fuze	
	Test No. 20 with Candidate No. 8 Sleeve on My04E2	126
30	Thermogram of Adapter Booster Thermosouple in Fuze	120
J-0	Test No. 00 with Candidate No. 14 Bleeve on MyC4E2	
	Fuze	100
57	Thermogram of Adapter Booster Thermocouple in Fuze	L
~ I	Test No. 20 with Candidate No. 1 Sleeve on M904E2	
	Fuze and Washer on Adapter	121
55	Thermogram of Adapter Booster Thermocouple in Fuze	A +
~ · ·	Test No. 20 with Candidate No. 10 Sleeve on My04E2	
	Fuze and Washer on Adapter Booster Ring	121
25	Thermogram of Fire Temperature Thermocouple for	
	Fuze Test No. 20	122
90	Test Set Up for Fuze Test No. 20	123
91	After the Fire - Fuze Test No. 20	124
92	Puze Test No. 21 - Thermogram of M904E2 Fuze	
	Protected with Candidate No. 5 Sleeve	126
93	Fuze Test No. 21 - Thermogram of My04E2 Fuze	
	Protected with Candidate No. 1 Sleeve	126
94	Fuze Test No. 21 - Thermogram of Fuze Protected	
	with the Candidate No. 14 Sleeve	127
95	Fuze Test No. 21 - Thermogram of Fuze Protected with Candidate No. 10 Sleeve	107
5. F	with Candidate No. 10 Sleeve	127
96	Fuze Test No. 21 - Thermogram on Inert M148 Adapter	
	Booster Thermocouple with Live M904E2 Fuze Protected	300
6.7	with Candidate No. 10 Sleeve and Washer Fuze Test No. 21 - Thermogram of Inert M148 Adapter	128
97	Booster Thermocouple with Live Fuze Mcc4E2 Protected	
	with a Candidate No. 14 Sleeve	128
98	Fuze Test No. 21 - Thermogram of Fire Temperature	161
J-0	Thermocouple	129
99	Fuze Test No. 22 - Thermogram of Fire Temperature	A 4
22	Thermccouple	129
100	ruze Test No. 22 - Thermogram of Inert MyO4E2 Fuze	
	Protected with Candidate No. 14 Sleeve	130

vi UNCLASSIFIED

Figure	Title	Page
101	Fuse Test No. 1 Themperam of Live Mid. Adapter	
	Booster - Inert My04En Puze Protented with the	
	Candidate No. 14 Sleeve	130
102	Fuze Test No. 22 - Thermogram of Live N 64Ez Fuze	
	Protected with a Candidate No. 1 Cleeve	1:1
103	Fuze Test No. 22 - Thermogram of Inert M14t Adapter	
-	Booster with Candidate No. 1 Sleeve	151
104	Fuze Test No. 21 - Thermogram f Live M. CAE. Fuze	
	Protected with Candidate No. 14 Sleeve	131
105	Fure Test No. 32 - Thermogram of Inert Ml46 Adapter	
	Booster with Live My04EP Puze Protected with	
	Candidate No. 14 Sleeve	132
100	Fuze Test No. 23 - Thermogram of a Live Mg. 4E2	
	Fuze Protected with Candidate No. 10 Sleeve	133
107	Fuze Test No. 22 - Thermogram of an Iner: Ml4c	
	Adapter Booster with Live M904E2 Fuze Protested	
	with Candidate No. 10 Sleeve	133
100	Exposed View of Thermocouples Installed in an	
	Adapter Booster	15
105	Faze Test No. 33 - Thermogram of a Live My(4E)	
	Fuze Protected with Candidate No. 1 Sleeve	13
110	Fuze Test No. 25 - Thermogram of an Inert M143	
	Adapter Booster Containing a Mys/4EC Fune Protected	
	with Candidate No. 1 Sleeve	13.
111	Fuze Test No. 23 - Photograph of Mk to Bome After	
	Cook-Off	140
112	Fuze Test No. 23 - Thermogram of an Inert My34E2	
	Puze Protected with Candidate No. 1 Sleeve	1.1
113	Fuze Test No. 23 - Thermogram of a Live M14c	
	Adapter Booster Containing a Fuse MyO4E2 Protected	
	with Candidate No. 1 Sleeve	1-1
114	Fuze Test No. 23 - Thermogram of an Inert My 4E2	
	Fuze Protected with Candidate No. 1 Sleeve	145
115	Thermogram of a Live M148 Adapter Booster Contain-	
	ing M904E2 Fuze Protected with Candidate No. 1	
	Sleeve	142
116	Fuze Test No. 23 - Thermogram of a Live MGO4E2 Fuze	-
	Protected with a Candidate No. 1 Sleeve	144
117	Fuze Test No. 23 - Thermogram of an Inert M14c	-
	Adapter Booster Containing M-04E? Fulle Protected	
	with Candidate No. 1 Sleeve	144
119	Puze Test No. 24 - Thermogram of a Live M904E2	
11	Puze Protected with a Candidate No. 10 Sleeve	145
119	Fuze Test No. 24 - Thermogram of an Inert M148	<b>-</b> - ₹
# # W	Adapter Booster Containing MGO4E2 Fuze Protected	
	with Candidate No. 10 Sleeve	145
120	Puze Test No. 24 - Thermogram of Inert Mp04E2 Fuze	477
120	Protected with Candidate No. 14 Sleeve	147
121	Fuze Test No. 24 - Thermogram of a Live M148	7 -4 (
* C T	Adapter Booster Containing MODULE Fuze Protected	
	with Candidate No. 14 Sleeve	147
	WIGH CONSTRUCT HOS IN DAILER SESSESSESSESSESSESSES	447

Figure	Title	Page
122	Fuze Test No. 34 - Thermogram of an Inert M904E2	- 1
1 22	Fuze Protected with Candidate No. 10 Sleeve	140
123	Fuze Test No. 24 - Thermogram of a Live M146	
	Adapter Booster Containing MyO4F7 Fuze Protected	• (1)
3.04	with Candidate No. 10 Sleeve	145
124	Fuze Test No. 24 - Thermogram of a Live M. 04E2	5.1.5
3 O.E.	Protected with Candidate No. 14 Sleeve	145
125	Fuze Test No. 4 - Thermogram of an Inert M145	
	Adapter Booster Containing MyO4E2 Fuze Protected with Candidate No. 14 Sleeve	3.7
126	Fuze Test No. 24 Fire Temperature Thermogram	149 150
127	Fuze Test No. 25 Fire Temperature Thermogram	150
126	Fuze Test No. 25 - Thermogram of a Live My04E2	100
# = C	Fuze Protected with Candidate No. 1 Sleeve	151
129	Fuze Test No. 25 - Thermogram of an Inert M14c	خرخا
149	Adapter Booster Containing M904E2 Fuze Protected	
	with Candidate No. 1 Sleeve	151
130	Fuze Test No. 25 - Thermogram of an Inert M904E3	
150	Fuze Protected with Candidate No. 1 Sleeve	153
131	Fuze Test No. 25 - Thermogram of a Live M148	-/_
± 0±	Adapter Booster Containing M904E2 Fuze Protected	
	with Candidate No. 1. Sleeve	153
132	Puze Test No. 25 - Thermogram of an Inert M904E3	
- 3	Fuze Protected with Candidate No. 14 Sleeve	154
133	Fuze Test No. 25 - Thermogram of a Live M148	
	Adapter Booster Containing M904E2 Fuze Protected	
	with Candidate No. 14 Sleeve	154
134	Fuze Test No. 25 - Thermogram of an Inert M904E2	
	Fuze Protected with Candidate No. 10 Sleeve	155
135	Fuze Test No. 25 - Thermogram of a Live M148	
	Adapter Booster Containing M904E2 Fuze Protected	
	with Candidate No. 10 Sleeve	155
136	Fuze Test No. 26 - Thermogram of a Live M904E2	
	Fuze Protected with Candidate No. 1 Sleeve Bonded	
	on with RTV 3145	157
137	Fuze Test No. 26 - Thermogram of an Inert M148	
	Adapter Booster Containing M904E2 Fuze Protected	
-	with Candidate No. 1 Sleeve	157
138	Fuze Test No. 26 - Thermogram of an Inert M904E2	
	Fuze Protected with Candidate No. 1 Sleeve Bonded	
	on with RTV 3145	158
139	Fuze Test No. 26 - Thermogram of a Live M148	
	Adapter Booster Containing M904E2 Fuze Protected	• = C
11.0	with Candidate No. 1 Sleeve Bonded with RTV 3145 .	158
140	Puze Test No. 26 - Thermogram of a Live M904E2	
	Fuze Protected with Candidate No. 14 Sleeve Bonded	150
9 1/9	with RTV 3145	159
141	Fuze Test No. 26 - Thermogram of an Inert M148	
	Adaptor Booster Containing M904E2 Fuze Protected with Candidate No. 1 Sleeve	150
	THE TRANSPORT OF THE PROPERTY	1 7

Figure	Title	Page
142	Fuze Test No. 26 - Thermogram of an Inert M904E2 Fuze Protected with Candidate No. 14 Sleeve Bonded	
	with RTV 3145	160
143	Fuze Test No. 26 - Thermogram of a Live M148	
	Adapter Booster Convaining M904E2 Fuze Protected	
	with Candidate No. 14 Sleeve Bonded with RTV 3145	160
144	Fuze Test No. 26 Fire Temperature Thermocouple	161
145	Fuze Test No. 27 Fire Temperature Thermocouple	161
146	Fuze Test No. 27 - Thermogram of Live M146	
	Adapter Booster Containing Fulse My04Et Protected	
	with Candidate No. 10 Sleeve Manufactured by a	
	New Source	165
147	Fuze Test No. 27 - Thermogram of a Live M148	
- ' '	Adapter Booster Containing MCGhEC Fuze Protected	
	with Candidate No. 1 Sleeve from a New Source	155
145	Fuze Test No. 27 - Thermogram of a Live M145	
	Adapter Booster Containing Fuze M904E2 Protected	
	with Candidate No. 10 Sleeve from a New Source	160
14	Fuze Test No. 27 - Thermogram of a Live M148	
± 1,5	Adapter Booster Containing MSO4E2 Fuze Protested	
	with Candidate No. 10 Sleeve Trop a New Source	
150	Photograph of Pit After Cook-Off Test	
151	Fuze Test No. 28 - Thermogram of a Live M14:	49 11
علد در علد	Adapter Booster Containing My04E2 Fuze Protected	
	with Candidate No. 14 Sleeve	10
152	Fige Test No. 28 - Thermogram of a Live M148	_ ~ ,
J	Adapter Booster Containing M904E2 Fuse Protected	
	with Candidate No. 10 Sleevs from a New Source	169
<b>1</b> 53	Fuze Test No. 29 - Photograph of Ablated Candidate	
درــ	No. 14 Sleeve After Test	170
154	Fuze Test No. 28 - Thermogram of a Live M14c	- : -
エノマ	Adapter Booster Containing MSO4ES Fuze Protected	
	with Candidate No. 10 Sleeve from a New Source	171
155	Fuze Test No. 28 - Photograph of Recovered Fuze .	172
156	Fuze Test No. 28 - Thermogram of a Live M148	( C.
100	Adapter Booster Containing M904E2 Fuse Protected	
	With Candidate No. 10 Sleeve	173
157	Fuze Test No. 28 - Fhotograph of Candidate No. 14	ن ۽ لد
157	Showing Slot Oriented Toward Fire	175
1 C C	Fuze Test No. 26 - Photograph of Candidate No. 10	اس) لمد
158		176
3.50	Sleeve with Slot Oriented Toward Fire	4 ( U
159	Fuze Test No. 29 - Photograph of Disc and Washer	7
3.60	of Candidate No. 10 Material	177
16 <b>0</b>	Fire Test No. 25 Thermogram of Fire Temperature	<b>1</b> ~ C
- ( -	Thermocouple	178
161	Fuze Test No. 29 - Thermogram of a Live M148	
	Adapter Booster Containing Fuze M904E2 Protected	/
	with Candidate No. 14 Sleeve	175
162	Fuze Test No. 29 - Photograph of a Typical	
	Detonation	180

Figure	Title	Page
163	Fuze Test No. 29 - Thermogram of a M140 Live Adapter Booster Containing M904E2 Fuze Protected with Candidate No. 10 Sleeve	181
164	Thermogram of a Live Adapter Booster - Fuze	181
165	Protected with Candidate No. 14. Sleeve	182
•	TABLES	
Table	Title	Page
1 2	Frequency of Specific Indicent Heat Pluxes Effect of Radiant Heat Shield on Total Heat Transmitted to a 3" Diameter x 3" Long Fuze Surface	2 3 4 <b>a</b>
3	Candidate Materials	
3 4 5	Results of Small Scale Burn Tests at NASA and NOL.	12
5	Performance of Insulating Materials Ranked According	10
6	to Their Insulating Properties Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of PF-1 (Candidate No. 8)	13 14
7	Effect of Accelerated Climatic Conditioning on Fire	- '
	Retardant Properties of BC-62 (Candidate No. 1)	15
8	Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of UP-1 (Candidate No. 14)	16
9	Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of N-NOL-7 (Candidate No. 12).	17
10	Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of N-NUL-213-A (Candidate No. 4	
11	Effect of Accelerated Climatic Conditioning on Fire	•
12	Retardant Properties of UR-3800 (Candidate No. 10) Effect of Accelerated Climatic Conditioning on Fire	19
10	Retardant Properties of P-NOL-FM (Candidate No. 7)	20
13	Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of TH-1 (Candidate No. 13)	21
14	Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of FM-30 (Candidate No. 5)	55
15	Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of MIL-R-6855 Neoprene (Candida No. 3)	te 23
16	Summary of Effects of Climatic Conditioning of Candidate Materials	<i>45</i> 35
17	Summary of Cook-Off Results of Thormally Protected H-6 Loaded Mk 82 Bombs with Live Fuzes	59
18	Cook-Off Results on Fuze M904E2 Equipped with Candidate No. 1 Sleeve and Mounted in Thermally	
10	Protected Mk ©2 Bombs	72
19	Boosters Mounted in Thermally Protected Mk 82 Bombs	103

Table	Pitle	Page
20	Cook-Off Results on Nose Fuze M904. 2 Equipped with Various Protective Coverings Bonded with RTV 737	134
21	Cook-Off Results on Thermally Protected Concrete Loaded Mk 82 Bombs Containing Live and Inert Nose Fuzes M904E2 with Various Protective Coverings	134
22	Assembled in Live and Inert M148 Adapter Boosters Cook-Off Results of Nose Puze M904E2 and Live M148	162
66	(T45E7) Adapter Booster - Combined Test Results	163

#### INTRODUCTION

A great deal of interest has recently been expressed over the response of ordnance items to flame engulfment. Both the USS FORRESTAL and USS ENTERPRISE tragedies have intensified this interest. These fires have vividly demonstrated the hazards of a fire on the flight deck of an aircraft carrier. Following the USS FORRESTAL catastrophe, the Russell Committee, investigating this tragedy, recommended that a program be initiated to extend the cook-off times of this incident. In response to the committee's recommendations, Naval Ordnance Systems Command assigned the Naval Ordnance Laboratory the task of determining the feasibility of extending the cook-off times of the Mk 80 series of hombs to five (5) minutes.

Under the ground rules established by NAVORD the solutions selected for study were to (1) be economically feasible, (2) be compatible with loading plant operations and (3) employ materials commercially available. Theoretical and experimental test studies were conducted on many materials. As a result of this program a new high melting point asphalt was developed for the interior of the bomb cases. Coupled with this fix, was a commercially available intumescent paint, which was applied on the outer skin of the Mk 80 bombs. This combination of fixes gave times in excess of five minutes. Unfortunately, the commercial intumescent paint was not weather resistant and effort on other external coatings was necessary.

In December 1968, the cook-off program was shifted to Naval Air Systems Command (NAVAIR). NAVAIR continued investigations of other materials and systems to provide greater and more reliable protection for unfuzed Mk 80 bombs under varying environmental treatment and rough handling conditions.

In January 1970, NOL was assigned the task to investigate the cook-off characteristics of the Nose Fuze M904E2, commonly used in the Mk 80 series of bombs and to provide solutions to extending the cook-off time. Since detonations are more probable if the Fuze M904E2 initiates first, it is desirable to extend the cook-off times of the Fuze M904E2 to times longer than the main explosive charge. This report describes the cook-off studies of the Fuze M904E2 and M148 (T45E7) Adapter Booster.

### THEORY

Basically, a large turbulent fully developed hydrocarbon fuel fire is a high temperature chemically reacting turbulent gas. The length and intensity of the fire is dependent upon the fuel supply, oxygen level and upon the heat available. These hydrocarbon fires are extremely high in soot concentration, and the flame temperature

$$q = \sigma(T_{\bullet} - T_{\bullet})^4$$

where

q = the heat flux BTU/hr-ft2

 $\sigma$  = the Stephan-Boltzman constant 0.1713 x 10<sup>-8</sup> BTU/hr-ft<sup>2</sup> °R<sup>4</sup>

T, = the average temperature of the fire

T. = the temperature of the outer surface of the case

Previous investigators (references 1 - 3) have characterized fires by reporting either an incident heat flux (based on  $T_*^*>T_*^*$ ) or a fire temperature. If one assumes the emissivity of the fire to be unity, then the incident flux, q, (in) is related to the fire temperatury by  $q(in)=\sigma T_*^*$ . Takata (reference 2) studied the frequency of incident fluxes in hydrocarbon fires of different sizes. The results of his work are shown in Table 1.

Table 1

Frequency of Specific Incident Heat Fluxes

Incident Heat Flux, BTU/Hr-Ft2	Prequency of Occurrence
<b>25,000 - 30,</b> 000	0.08
<b>30,000 - 35,000</b>	0.12
35,000 - 40,000	0.18
40,000 - 45,000	0.21
45,000 - 50,000	0.29
50,000 - 55,000	0.12
<b>25.000 -</b> 55.000	1.00

Based on the work of Takata and other investigaters, incident heat fluxes of 30,000 BTU/Hr-Ft2 and 45,000 BTU/Hr-Ft2 were selected

as being representative of liquid hydrocarbon fires. The fire temperatures corresponding to 30,000 and 45,000 BTU/Hr-Ft<sup>2</sup> are 863°C and 981°C respectively.

The Fuze M904E2 surface to be protected thermally is approximately 3" diameter by 3" long. The front of the fuze cannot be protected easily because of an arming vane which must turn freely. If we take the average flame temperature of the jet fuel fire as  $1600^{\circ}$ F nominal, the heat flux produced is approximately 36,000 BTU/Hr-Ft². If it is assumed that the fire completely surrounds the fuze then the area exposed to the radiative (90%) and convective (10%) heat flux is  $(\pi)$  3 in x 3 in = 28.2 in² or  $\frac{28.2}{100}$  = .195 Ft². Based on

this area the heat flux to the fuze is  $0.9 \times .195 \times 36,000 = 6300$  BTU/Hr radiative and  $0.1 \times .195 \times 36,000 = 700$  BTU/Hr convective. If thermal protection is to be provided for 10 minutes then a total of approximately 1/6 of these values, 1050 BTU radiative heat and 116 BTU convective heat must be dissipated or otherwise prevented from reaching the fuze.

Since the majority of the heat involved is radiated, a radiation shield will eliminate a large amount of the heat input to the fuze. The total heat inputs to a fuze surface are tabulated on Table 2 based on the use of highly polished aluminum or gold.

#### Table 2

Effect of Radiant Heat Shield on Total Heat Transmitted to a 3" Diameter x 3" Long Fuze Surface

#### Shield Material

Characteristic	Aluminum High Polish	Gold High Polish
Emissivity	0.1	6.02
Radiative Heat in 10 min. (BTU)	105	35
Convective Heat in 10 min. (BTU)	116	116

Note that the heat input to the fuze with a radiative shield is \$1-87% less than the \$166 BTU input if no shield is used and if the fuze is considered to have an emissivity of one. However, because of the cost involved in a radiation shield and the handling which these fuzes receive, this approach was rejected.

Another method of delaying the arrival of the cook-off temperature to the lead and booster explosive in the fuze is to provide an insulative foam layer on the surface of the fuze. A typical foam insulation is assumed to have a density of 4 lbs/ft³, specific heat 0.3 BTU/lb °F and thermal conductivity of 0.017 BTU-ft/hr-ft² °F. Calculations have been made to estimate the thickness of insulative foam needed at various heat fluxes to reach 300°F in 10 minute explosure to the flux. The results of these calculations are shown in Figure 1. This type of an approach was abandoned because the thickness of insulation required would be unacceptable.

#### MATERIAL CONSIDERATION

It was decided to investigate fifteen insulation materials for the exterior cylindrical portion of the Fuze M904E2. This was done by a screening test on the basis of such factors as fire performance (conducted at the Ames Research Center and NOL), physical properties, cost considerations and the results of exposure to thermal shock and temperature and humidity cycling. Table 3 lists the fifteen (15) candidates and the source of finished sleeve, or in some cases, source of material from which sleeves were fabricated.

# TABLE 5 Candidate Materials

		Chidiante Materials	
Candidate No.	Code Name	Description	<u>Joars</u> e
1	BC-62	Proprietary Intumescent Ratter	Goodyear Hulber Company 1144 E. Market St. Akron, Ohio
2	N-NOL-300	Neoprene (MIL-R-1007 - Fatricated Parts)	.t.cswell Hutter Company 1117 Shackamaxon St. Philadelphia, Pa.
3	<b>N-NOL-</b> 6855	Neoprene (MIL-R-O'S: Sheet)	Aberdeen Proving Ground Aberdeen, Maryland
	The same of the sa		Dieeves fatricated by Gamp Corp., Aberdeen, Md.
4	N-NOL-213A	Neoprene, Boric Acid, Phenolis	Uniroyal Ructer Company Mishawaka, Indiana
5	<b>PM-</b> 30	Proprietary Filled Polyester	Avel Corporation Domesi, Massachusetts
6	P-NOL-	Polysulfide Rubber (MII-3-1173)	Products Res. & Chem. Co. -11-41' Jersey Ave. Gloucester City, N.J.
7	P-NOL-FM	Polysulfide Hubber and	Products Res. & Chem. Co. Gloucester City, N.J.
		<pre>// Tris .,3 Dibromograpy! Phosphate (Firemaster)</pre>	Michigan Chemical Co. 811 East Ohio Chicago, Ill <b>inois</b>
Ą	PF-1	Proprietary Filled Polysulfide Epoxy	Universal Propulsion Co. 46 Riverside, California
7	E-NOL-6	Epoxy Adhesive Paste (WS-13045A) and	Hysol Div. of Dexter Corp Pittsburgh, California
		5% Phenolic Microballoons	Union Cartide, Bound Brook, N.J.
10	<b>UR-3</b> 800	Butadiene-Acrylonitrile Rubber Boric Acid, Phenolic (W5-7959)	Uniroyal Rubber Co. Mishawaka, Indiana B.F. Goodrich Aerospace 500 S. Main, Akron, Ohio
11	UR-624	Proprietary Polyurethane, Boric Acid, Phenolic	Unincyal Rubber Company Mishawaka, Indiana
12	N-NOL-7	Neoprene and 10% Firemaster	Unircyal Rubber Company Mishawaka, Indiana
13	TH-1	Proprietary Pilled Epoxy with Microballoons	Thickol Chemical Company Brigham City, Utah
14	U <b>P-</b> 1	Proprietary Filled Polyester	Unique Products 2014 Cyprus St. Ganta Ana, California
15	PL-44	Froprietary	Insulation Systems Inc. 17 South Richey St. Santa Ana, California

4a UNCLASS IPTED




FIG. 1 FOAM INSULATION THICKNESS NEEDED FOR FUTE PROTECTION FOR 10 MINUTES

Specimen Preparation and Fire Tests at NOL

Two sizes of specimens were used for the candidate material study. Flat aluminum plates  $9" \times 5" \times 1/6"$  were coated with 1" of the test materials. These were instrumented with thermocouples and subjected to a Meeker burner flame. The heat flux was adjusted to 10 BTU/Sec-ft<sup>3</sup>. A continuous recording was made of the temperatures associated with each test. A mask of rigid asbestos  $12" \times 12" \times \frac{1}{2}"$  with a 2.50" square in the center, was placed against the face of the sample assembly. The astestos assembly equipped with the sample plate was then placed over the burner. The aluminum plate was outfitted with a thermocouple in order to measure the backface temperature. The backface thermocouple was kept in place by means of a fire brick which also acted as an insulator, allowing minimum heat losses.

Specimen Preparation and Fire Tests at NASA Ames

The Ames Test Pacility utilized an oil burner which burned jet fuel at the rate of approximately 1½ gal/hr. The chamber was fire-brick lined, and the combustion products were exhausted out the top rear of the unit. For these tests the flow rate to the burner was adjusted to maintain 10 to 10.5 BTU/ft² sec (36,000 - 37,800 BTU/ft² hr) total heat flux. The temperature at the hot face of the sample was maintained at 1700°F minimum throughout the test. The samples used for this test were 2-7/6" x 2-7/6" x ½" specimens. A schematic of the sample assembly is shown in Figure 2. The samples were backed with 1/8" thick 2024-T4 aluminum alloy, bonded to the surface with a high temperature epoxy. The back plate had a 1.25 in. diameter hole, to which was bonded a 1" diameter slug calorimeter of the same class and thickness. The aluminum back or supporting plate had a dual function. First it represented the thickness of the actual fuze skin, and second it acted as a supporting plate for the samples in the test apparatus and prevented any warping of the insulating sample during the test. The test samples were placed in a mask of asbestos 12" x 12" x ½" thick with a 2-7/8" square cut in its center and then placed in the oil burner. The aluminum backface temperature was recorded continuously for the test duration.

Temperature and Temperature and Humidity Treatment

The temperature and humidity tests were employed to get preliminary information on the ability of the materials to withstand adverse climatic conditions of temperature and humidity. The total test is made up of two complete 14-day "JAN temperature and humidity cycles". The basic 14-day unit or "JAN temperature and humidity cycle" consisted of cycling the samples nine times between the extremes of  $+160^{\circ}$  F (95 percent RH) and  $-65^{\circ}$  F with additional storage at  $+160^{\circ}$  F (95 percent RH) and  $-60^{\circ}$  F. The first step was to store the test item  $(2-7/3)^{\circ}$  x 2-7/3 x 1/3 aluminum plate with test insulator cemented on with epoxy cement) in a cabinet at  $-65^{\circ}$  F




FIG. 2 SAMPLE PLATE ASSEMBLY

for two hours. The temperature was then raised to +160°F (95% RH) and the test item maintained at this temperature for 14 hours. The temperature was then lowered again to -65°F and the samples maintained at this temperature for two hours. The operations were repeated Monday to Friday. After raising the cabinet temperature to +160°F (95% RH) on Friday evening, these conditions were maintained until 0800 on the following Monday. At 0800 Monday, the sequence of operations was carried out again until Friday of the second week. On Friday of the second week the cabinet temperature was reduced to -co°F instead of -65°F and this temperature was maintained until the beginning of the third week. The second cycle then began. Two such cycles were applied in testing these insulators. In addition, samples were stored at  $-65^{\circ}$ F for 26 days and also at  $160^{\circ}$ F for 28 days in order to determine which conditions were the most severe for the various samples. Hardness measurements were taken every week to determine any post-curing or degradation. Hardness measurements were made with the Shore Durometer Hardness Tester Type A-2. The samples were allowed to come to room temperature before the measurements were made. Samples 1, 2, 3, 4, 10, 11, 12 (refer to Table 3) (rubbery type sheet materials) were cemented to the aluminum plate by epoxy cement and allowed to cure overnight. All of the other plates were prepared by applying a mixed resin system to one surface of an aluminum plate with a spatula. The proper thickness was obtained by machining the finished samples whenever possible. Many of the mixed resin systems (samples No. 5, 6, 7, 8, 9, 13, 14 and 15 (Table 3)) were quite viscous and difficult to mix.

A single Chromal-Alumel thermocouple was attached to each specimen by means of aluminum backed tape and was held in place by means of a good insulator such as fire brick.

Results and Conclusion of Burn Tests

Prior to testing the specimens, the thickness of each of the insulating materials was determined in several locations expecially in the center around the slug calorimeter.

The individual test specimens were than exposed to the flame with a heat flux of 10 to 10.6 BTU/ft<sup>2</sup> sec. Only the coated surface of the flat plate specimens were exposed to the flame. The fire temperature was  $1750^{\circ}$  F.

Time-temperature plots were recorded and exposure was terminated when the temperature reached 400°F. The test specimens were examined after exposure and photographs taken of some of the specimens after the test are shown in Figure 3.

After an induction period of approximately 35 seconds the time-temperature curves were essentially linear. Figure 4 is a typical time-temperature plot. Since different thicknesses were involved with each sample, the data were normalized to account for

UNCLASSIFIED




FIG. 3 PHOTOGRAPH OF SPECIMENS AFTER EXPOSEMENT WANT OF 1737 F




FIG. 4 TYPICAL TIME - TEMPERATURE PLOT OF BACKFACE TEMPERATURE ON EXPOSURE TO 1750°F FLAME

differences in thickness. Both the NASA burn test results and NOL burn test results are shown in Table 4. The thermal tarriers are ranked in the order of their insulating properties in Table 5. From Table 5 it can be seen there is reasonable agreement from both types of tests. One of the candidates produced an outstanding firm and rigid char. Its lower ranking was believed to be due to a crack at the thermocouple position and points up a possible serious disadvantage of small scale tests of this nature. Small imperfections sometimes cause catastrophic failures, whereas, in actual large scale fire tests, the temperature effects of the crack are averaged over a large surface area.

After completion of the small scale fire tests, five candidate samples were discarded from the program as no longer promising. These candidate samples were No. 9, No. 15, No. 11, No. 6 and No. 2. The remainder of the samples were subjected to -65°F, -65°F to +160°F (95% RH) and +160°F with weekly withdrawls. Figures 5 through 14 are plots of **Shore A** Durometer hardness as a function of time for the three conditions of exposure. The change in hardness was measured since this characteristic is related to the change in crosslink density of a polymeric network. Tables 6 through 15 represent the times to reach 200°F, 400°F and the temperature at the end of 10 minutes after exposure to a Butane flame of 2000°F. The changes in fire protection were qualitatively followed in this manner. Table 16 includes various observations associated with the material treatment.

Figure 5 shows the effect of accelerated climatic conditions on the physical and mechanical properties of candidate No. 8 material, indicating that the material looses about 100% of its strength after 28 days of exposure in the JAN cycle changing from a rigid polymer to a soft putty like material. Table 6 indicates that the material also loses part of its thermal insulating properties when cycled between -65°F and +160°F. However, the insulating properties are still quite good (Table 6).

Candidate No. 1, intumescent Neoprene rubber, appears to possess good low and high temperature resistance. Figure 6 indicates no significant changes in crosslink density. Table 7 indicates no loss of fire protection after one month of storage at high and low temperatures.

Candidate No. 14 was affected by environmental storage. Table Sindicates that the cycled conditions were the most severe. After 28 days in the JAN cycle, the material appeared to have lost part of its insulating properties (Table C). Figure 7 indicates a degradation in crosslink demaity at +160°F and after JAN cycling. The material also cracked badly after 28 days of JAN cycling. It also appeared to have lost its adhesion to the aluminum substrate.

Candidate No. 12 was also affected by accelerated aging. Figure 8 shows that when the material was cycled depolymerization occurred. The rubber compound changed from a soft rubbery material

Table 4 - Results of Smell Scale Furn Test at NASA and NOL

	OF S					NCLA: OLTR		IED 124							
Ø	Time to 400° F Thickness	1	4514	1200	1398	3744	1515	1346	1745	4074	953	7452	1200	1745	1673 1760 1504
NOL Test Results	Time to 400°F in Sec.	09	949	300	345	<u>५</u>	909	777	276	ತು ಭ ೧	268	939	300	57€	555 660 564
	Thickness Inches	0	0.156	0.250	0.250	0.173	0.330	0.330	0.330	0.125	132.0	0.250	0.250	0.330	0.330 0.375 0.375
ន	Time to 400° F Thickness	1	1461	3001	1100	1416	1102	1000	1194	2080	637	1040	1016	1565	1256 1143 1056
NASA Test Results	Time to 400°F in Sec.	50	260	180	330	245	280	)†£	350	SC	195	255	255	180	245 255 245
	Thickness Inches	O	0.178	0.179	0.300	0.173	0.254	0.340	0.293	0.137	0.306	0.245	0.251	0.115	0.195
	Candidate Number & Code Name	Control	No. 1 BC-62	No. 2 N-NOL-3065	No. 3 N-NOL-6855	No. 4 N-NOL-213A	No. 5	No. 6 P-NOL-3	NO. 7 P-NOL-FM	No. 8 PF-1	No. O E-Nolmé	No. 10 UR-3800	No. 11 UR-624	No. 12 N-NOL-7	No. 13 TH-1 No. 14 - UP-1 No. 15, PL-44

Table 5

Performance of Insulating Materials Ranked According to Their Insulating Properties

Candidate No.	NASA Ranking	Candidate No.	NOL Ranking
8	PF-1		PF-1
10	N-NOL-"	<u>.</u>	BO-12
1	BC-∪7	7 6.4	N-NGL-013A
1,	N-NOL-: 3A	10	U.A-1.000
13	TH-1	14,	UP-1
7	P-NOL-FM	17	P-NOL-FM
14	UP-1	1	N-NOL-
10	UR-3500	13	TH-1
11	UR-Ci.4		FM-30
j	FM-30	15	PL-44.
3	N-NOL-6855	3	N-NOL-6: 55
15	PL-42,	C	P-NOL-3
2	N-NOL-3065	11	UR-624
6	P-NOL-3	2	N-NOL-3065
9	E-NOL-O	9	E-NOL-(

UNCLASSIFIED NOLTR 71-124

Table 6

Effect of A	ccelerated Clima	tic Conditioning PF-1 (Candidate	on Fire Retar	Fire Retardant Properties 8)	ຮູ້
Environment	Th1ckness Inches	Storage Time (weeks)	t200°F Minutes	t.00°F Minutes	Tlo Minute
Control	461. 163	<b>-</b> 0	7.6	00 47	290 245
E	1.881. 282 282	ผผพ	લ્ <b>ય</b> ું એક્ષ	×××10 ×10	000 440 500 500
-65°F - 160°F	202.	, କଥାଚ	020.	004. 004.	270 310 420
160° म	2001 2005 11015	nom	សសក ស្ន <b>ុ</b>	000	247 447 247

14 UNCLASS IF IED

Effect of A	coelerated Cl1ma	Effect of Accelerated Climatic Conditioning of BC-62 (Candidate	On Parch	Retardant Properties	Les
The market of the	Thickness Inches	Storage Time (Weeks)	t 200° F Minutes	t°CO°F Minutes	Tic Minu:
Control	(4 (1 (1 1 - (1) (1 6) (1) (1	ન(1)	ري نو نو	र्यंत	(2. 0)
(E) 0 = 11		ed (1992)	3.91. 1.27.10	2007 7777	(2) 100 85 (1) 13 87 (1) 14 87 (1) 14 87
	5.00 m 5.00 m	m( (*)-4		000 777	000 100 100
n. Crrr el	9000 9000	ક <b>ન્ય</b>   λ ( <sup>17</sup> ,~		derig	0000 0000 0000

15 UNCLASSIFIED

Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of HP1 (Candidate No. 1h)

	Jo	of UP-1 (Candidate No. 14)	No. 14)		
Environment	Th1ckness Inches	Storage Time (Weeks)	t <sub>200° F</sub> Minutes	t400° F Minutes	Tic Minutes
Sontrol "		ডোগাৰ	သာဝက လက်လေ	C.W3	പയ പ്രത്യ പ്രവര
E. 202 = = = 100	.266 .241 .261	ଳ ଓ ୯୯୭	പുപു ഗുമ സ്ത്രസ്	. 10 cm∪ -17 cm	74 8 45 7 8 44 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
-52°F - 160°F	.249 .248 .251	⊣ W M-7	ကကကင	16000000000000000000000000000000000000	640 630 750
F = =	. 233 . 242 . 273	ณ ๗๘	10.1 10.0	গ্ৰেন কৰ্ণ	730

\*Sample Aflame

UNCLASSIFIED NOLTR 71-124

Table :

i.e.c.	Tlo Minutes	0.72	*		47   1 
rdant Propert	TACO F Minutes	e e e e e e e e e e e e e e e e e e e	0,220	· ( ) ( )	
on Fire Ressio. 10)	tgoor F Minutes	⊱ન્ય પ્રાફે.	িৰ্ক্তু এএল):	ing to	ed ed ed
Effect of Accelerated Climatic Conditioning on Fire Reperdant Properties $N-NOL-\gamma$ (Candidate No. 17)	Storage Time (weeks)	৫৫ ১৮৮	H · JA	ਜਾ∻ਕ	<b>⊢</b> (:
	Thickness Inches		105 1064 177	4 00 4 00 4 00	
Effect of Ac	Environment	Control		-65° F - 160° F	ir.

\*Thermanaurple dame lande, cample sapped in venters.

10 10 10 10 10 10	Environment		irt	-65°F - 160°F	
Acoelerated Clin	Thickness Inches	(- () - () - () () () - () () ()	: — ्ट (व (व ) त्यां व्य (वृद्धां व्य	2000 2000 2000 2000 2000 2000 2000 200	5.00 5.00 5.00 5.00 5.00 5.00 5.00 5.00
inablo Conditioni NOL-215-8 (Candida	Storage Time (Weeks)	e-tribus.	.ed ं ) () 3- f	e4 ( ) (1)-4	ल (च (५) र
ate Mar 1)	Scoton Minutes		11 11 2 pm 11 11 11 11 11 11 11 11 11 11 11 11 11	်ပ္သက္လ လွ်က်က်လ	oj-vi-vi movivel
Recerdant Properutes	Tanates	# 21 <u>1</u>	**************************************	10 (0 t=\0 (1 ) (1 (1)	ウンロン ・ロ・ かいたか
lex	S X marke	2 2 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	୍ଟ୍ରମ୍ବର 19 ମମ ଏହାଡ଼ିଆ	10000000000000000000000000000000000000	810000 aretet.u -r-r0%,

18 UNCLASSIFIED

**BEST AVAILABLE COPY** 

12 12 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15	17 (17 (17 (17 (17 (17 (17 (17 (17 (17 (		0			
		4 (1 ( ) ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) (	C1 (2/2) / (1 - (4/2) / (1 - (1/2) / (1/2)	or or or or each ready	Criston Criston Criston	
		et satali	e (C) O mil	<del>y-</del> f €2 et i= ‡	er Com	
			र क्षेत्रक सम्बद्ध	1,11,100 of of of of 1,7,7,7	-1 BA-1	
	14 m 5 Vi 7 Vi 8 Vi 9 Vi 12 Vi	**************************************	2+1 (2 € . • • + + 1 • 1 * (2 € . € . € . € . € . € . € . € . € . €	. O G C ed ed ed ed Z . Z . Z	Constant et ed ed ed Zozozaz	• ••
· ·			(J. C. C. C.) 이 (J. C.) 고 (C. C.)	Colored Colored etelever	Considered Soft Admin Soft Considered	

19 UNCLASSIFIED

**BEST AVAILABLE COPY** 

Effect of Ad	ccelerated Clima of	Effect of Accelerated Climatic Conditioning on P-NOIMFM (Candidate	Fig.	Rotandaut Propertios )	ت ن
Frvironment	Thickess Diches	Storage Time (Weeks)	toco'F	FLOCER Minutes	Tic Minute
Control	3.3.3. 3.3.3.3 3.3.3.3	et Carr	. ඔ ු - † ආා	000 777	000 HC0 MMM
न ्ह <sub>े</sub> ं -	1375 2500 2000 2000 2000 2000 2000 2000 20	u ന- <del>-</del> =	् <b>०</b> यस्क	0 G (t) 7. <b>3</b> ()	471-1 471-1 471-10
4°55 - 165°5-	40.20 40.20 20.20	ed ೯೩೧%ರ	ು೦ಎ ೬ ಄ೱ೮ಀ	2000 es	0000 000 000 000
10° F	885 133 133 133	ಈ ೧. ೮೩	ಟ <b>ು</b> • • • • 4 MRH	೧ ೧ಎ೯೮ ಈ • • • ಸರಗಳ	೧೦೦೪ ೧೯೩೮ ೧೩೮೨

20 UNCLASSIFIED

ranle 15

Resardant Properties Effect of Accelerated Climatic Conditioning on Fire of TH-1 (Candidate No. 13)

	Thickness	Storage Time	t 200° F		Tlo Minutes
Hry Ironnenc	Diches	(weeks)	Minutes	Minutes	£.,
Control	2000 2000 2000 2000 2000	ಂಗುವ	400	C4 .	00.0 00.0 00.0 00.0
84 C C	.24: .24: .331	ಈ೮೮%	wome. wome	(1)((1) . )	99 N#3
E 000 - E 000 - E	#3.56 #3.56	F4 (U M)	യയയ പ്പ്ഗ്	31C.O	>1024 560 >750
<b>E.</b>	\$224 .000 .75.	പ്രഭാഗ	्रक्ट. नि. ^	mu 0 .∶∢7	25.50 Ex

Jample Aflame

71 UNCLASSIFIED

UNCLASSIFIED NOLTR 71-124

Effect of Acceler  Environment  Control  -65°F  -65°F  160°F	celerated Clima of Thickness Inches	Ta Con Stora Stora	No. 7 The Minute Minute (200°	Retardant Properties  F thoo'F  Alnutes  7.6 6.0 7.8 8.8 5.9 10.0 9.8 >10.0	ET
	241	au m	ດາ ດາ ພັນ.	<b>រ</b> ុះព្	0 0 0 0

22 UNCLASSIFIED

Effect of Accelerated Climatic Conditioning on Fire Retardant Properties of Air-R-6555 Neoprene Table 15

	T.C. Minutes	0 W.W	シング かい いち かい こうかい こうかい こうかい こうかい こうかい こうかい こうかい こう		03300 03563 43544
(Candidate No. 3)	t <sub>4CC°</sub> F Minutes	armo 047	० व स्व । १७१४ व	5.6 5.3 5.3 shut off after 10 was aflanc.	(
	t200°F	in-or	ಗಣಗಗ	1.0 2.2 1.0 2.0 Fuel sh	्द्र् संसत्त
	Storage Time (weeks)	യ നഷ	ಗಟ್ಟಾ	HUM#	H C M#
	Thickness	2000	255 272 261 250	9.44.64 9.44.64 9.85.64	. 6733 1733 173 173
	Environment	Control	#4 0 C C C	-65° 7 - 160° 7	3.60° F

\* Material fell apart in sheets.




FIG. 5 SHORE A DUROMETER HARDNESS VS TIME FOR THESE TEMPERATURE EXPOSURES




FIG. 6 SHORE A DUROMETER HARDNESS VS TIME FOR THESE TEMPERATIFE





FIG. 7 SHORE A DUROMETER HARDMESS VS THEE TEMPERATURE TYPOSURES



TIA. P SHOPE A TOO METER HARDMISS VS TIME FOR SHIPS ENVERAGE ERROSERS

to a jell. The sample also discolored, changing from an off white color to a reddish brown. The fire retardancy of the material, shown in Table 9 does not appear to be affected by the environmental treatment. On a close examination of the rubber it appears as though the tris 2,3 dibromopropyl phosphate was not compatible with the rubber stock.

Figure 4 and Table 10 indicate that the Candidate No. 4 was affected by both the high temperature and low temperature storage conditions. The material appears to show a marked degradation in physical properties and thermal protection after low temperature storage, and exposure to the 25 day JAN cycle.

Figure 10 indicates the changes in mechanical properties and thermal protection of Candidate No. 10. The rubber appears to be post curing at the elevated temperature, the performance in a fire is shown on Table 11.

The physical properties of Candidate No. 7 do not appear to be affected by the accelerated temperatures (Figure 11). The material was relatively soft at the onset, and appears to assume a permanent set on aging at  $\pm 160^{\circ}$  F. Table 12 indicates the material loses its intumescent character at  $160^{\circ}$  F.


The physical properties of Candidate No. 13 is shown in Figure 12; it was relatively unaffected by the storage conditions. The material, however, was extremely brittle and had plor impact resistance. The thermal properties were extremely poor and are shown in Table 13.

Figure 13 and Table 14 indicate Candidate No. 5 was somewhat affected by high temperature storage. Shrinkage/expansion characteristics appeared to be a problem area (Table 16).


Candidate No. 3 was relatively insensitive to the storage conditions at high and low temperatures as shown in Figure 14 and Table 15. The sample burned quite vigorously when the burner was removed from the sample.

Candidate No. 13 was eliminated on the basis that it would be incapable of withstanding the treatment it would experience in the Fleet. Candidate No. 3 was also eliminated because of its flammability.

FIG. ? SHOPE A DURE WETER HARTLESS VS THE




1.0418 71 144




OF A THE COMPLIANT STORAGE THAT CONTRACT

THE A STREET HERE AND THE HARDSHESS OF THAT





FOR THESE TEMPERATURE EXPOSURES



OUR ISOMEDIAL STORAGE TIME (WHIES)

FIG. 10 SHOWE A DUROMETER HAPDNESS VS TIME FOR THESE TEMPERATURE ENDOSHRES




FIG. 13 SHORE A DUROMETER HARDNESS VS TIME FOR THESE TEMPERATURE EXPOSURES




FIG. 14 SHORE A DUROMETER HARDNESS VS TIME FOR THESE TEMPERATURE EXPOSURES

## Table 16

## Summary of Effects of Climatic Conditioning of Candidate Materials

Material	Results
PF-1 Candidate No. 8	Changed in hardnessbecame soft. Marked degradation in physical properties. Lost some thermal properties.
BC-52 Candidate No. 1	No noticeable change.
UP-1 Candidate No. 14	Material warped at high temperature. On burning it pulled away from metal. At JAN cycle, thermal properties reduced and cracking occurred.
N-NOL-7 Candidate No. 12	Tris 2,3 DiBromopropyl Phosphate not compatible with Neoprenebecame soft and mushy. Lost intumescence.
N-NOL-213A Candidate No. 4	Lost its fire protection and physical characteristics.
P-NOL-FM Candidate No. 7	Lost its intumescence at 160°F.
UR-3800 - WS 8939 Candidate No. 10	Post curedproperties improved with age. Produced outstanding char.
Neoprene MIL-R-6855 Candidate No. 3	No noticeable change.
Candidate No. 13	Material very brittle; questionable handling ruggedness.
Candidate No. 5	Lost some of its thermal properties at high temperature storage. Shrinkage/expansion characteristics were noted as possible problem area.

## FIELD TEST PROGRAM

Concurrent with the laboratory program a field test program was planned and begun. Sleeves were fabricated and placed on M904E2 Puzes. These were equipped with thermocouples, assembled to Mk 82 bombs and fire tested at White Sands Missile Range, New Mexico.

## FAST COOK-OFF TEST ARRANGEMENT

Flame envelopment tests were performed by suspending the test item approximately 36" from the surface of 2000 gallons of JP-4 fuel. A 35' x 35' x 1' enclosure (pit) was constructed from sand and polyethylene sheet. The pit was located in an excavation 55" x 55" x 10" deep in order to minimize the effects of wind currents. The pit contained the fuel with two inches of water beneath the fuel to provide a level surface. The fuel was ignited with four thermite grenades modified with electric squibs. were placed in four locations so as to initiate burning over the entire fuel surface, as rapidly as possible. The fire tests were conducted when the wind velocity was five knots or less, to ensure complete engulfment of the test item. Generally, the wind velocity at ground level was approximately twice as high as in the pit. Schematics of the field test arrangement are shown in Figures 15a and 15b. The instrumentation trailer was housed in an earth barricade to protect the occupants and instruments during the test. A trench 800 feet long x 1 foot deep x 1 foot wide was dug, in order to house the cables. After placement of the cables they were then covered with sand. A smaller earth barricade of 4' x 4' x 4' was dug approximately 50 feet from the burn pits in order to house the reference junction and to protect it from the intense heat. A preliminary specification for fast cook-off test of the Mk 30 series of low drag bombs is contained in Appendix C.

#### INSTRUMENTATION

A Vidar Data Acquisition System was used to measure the thermocouple data. This equipment is capable of scanning up to 1000-three wire guarded input channels and recording on paper tape. Approximately half-way during the program a magnetic tape recording capability was added which simplified the data reduction process. The system measured d.c. voltage between one microvolt and 300 millivolts which could be translated to a temperature range between -30°F and 3000°F. These modes and ranges of measurement were remotely selected and were programmed in blocks of 10 for easy insertion into the computer. The usefulness of this system is its high degree of noise immunity from both common and normal mode interference. The system normally scanned at the rate of 5 pts/sec although faster scanning rates were sometimes used. Twenty-eight gauge chromel-alumel thermocouple wire was used to instrument the test item, internally and externally. The external thermocouples were used to measure the fire temperature and were located symmetrically around the test item. Ice was used as the reference junction. Color motion pirture dameras were used to cover each test and were located local feet from the test. Normal frame rates of 24 fps were used. Still camera coverage was employed for documentary purposes. The test firings were viewed on closed circuit television and a video tape recording was made of each shot.

The capability to record the magnitude of pressure resulting from a bomb detonation was afforded by the use of Pytrex pressure transducers. Since the detonation of an explosive in air causes




FIG. 155 SCHEMATIC OF HEIR HIST ARRANGIMENT




FIG. 156 TEST SHE LAYOUT

a relatively large amount of energy to be released in a short time, the shock wave starts with an initial high pressure near the explosive and eventually decays to a sound wave at some distance from the charge. The Bytrex transducer utilizes semi-conductor strain gages as the sensor. The gages are bonded to a force member which is attached to the center of a pressure responsive diaphragm. When the diaphragm is subjected to pressure, the force member is compressed. This compression induces a strain and changes the electrical resistance of the strain pages. The strain gages are connected to form a wheatstone bridge. When excited with a constant voltage, the change in resistance of the gage causes an unbalance in the wheatstone bridge and produces a voltage proportional to the applied pressure.

The signal conditioning equipment consists of two separate components. Transducer excitation was provided by a well regulated power supply capable of providing J-30 volts d.c., when operated in the constant voltage mode, and 0 to 100 milliamps when operated in the constant current mode. The second signal conditioning component is provided for bridge balancing and shunt calibration of the transducer. The electrical calibrations were achieved by shunting one arm of the wheatstone bridge with a pre-determined resistance and measuring the voltage produced by the resulting bridge unbalance. D.C. amplifiers were used to increase the transducer output to the level regimed by the tape recorder AM record amplifier for full scale calibration. The amplifiers were differential amplifiers and had continuously variable gain from 1 to 1000 and a maximum output of 10 volts at 100 milliamps. The upper band pass of the amplifiers was 100 KHz.

Standard commercially available magnetic tape was used to record data on all tests. The tape recorders were supplied by the White Sands Missile Range. The recorders were used in the CC KHz mode and all data was taken at a tape speed of to inches per second. The instrumentation is illustrated in block form in Figure 18.

A pin switch control circuit was set up and used in this program to establish the origin of any detonation or deflagration occurring in the cook-off of a Mk % bomb. Thermocouple wire was used as the sensing element. When a detonation or deflagration occurred, a switch was closed discharging a capacitor and triggering an oscilloscope equipped with a polaroid camera. The signal was also recorded on a tape recorder. By judiciously placing the probes at various positions in a Mk of bomb it was possible to ascertain the origin of the detonation wave. A complete description of the pin probe circuit is shown in Appendix A.

## HARDWARE DESCRIPTION

The Fuze MGO4E2 is the most extensively used fuze in the Mk 60 series of bombs. Preliminary test data from the Naval Weapons Laboratory, Dahlgren, Virginia, indicated that the Fuze MGO4E2 was

THE STREET STREET, STR




FIG. 16 THE PAR PECONDING SYSTEM

likely to be a limiting component in cook-off when protection was provided on the bomb. Because of its high usage by the Fleet, cook-off protection of the Fuze My04E2 was given first priority.

The Nose Fuze M904E2 weighs about 2-1/3 pounds and it has an aluminum body! it is approximately 9-1 inches long and it has a 2.0 inch thread which screws into the M148 Adapter Booster. When assembled into the bomb the fuze protrudes approximately 4-1/8 inches (Figure 17). The M904E2 Fuze Booster contains approximately 74 grams of tetryl. Figure 18 shows a sectional and exploded view of the fuze in the unarmed position.

The arming of the Puze M904E2 is accomplished by rotation of an arming vane and it must turn freely in the air stream when the bomb is released.

There are three positions on the side of the fuze which must not be covered by any fixed insulator that is employed for fire protection. One is the observation window where the safe or armed position of the fuze is observed. The second is a stop screw which needs to be removed for arming times below 6 seconds. The third is the setting index locking pin which when depressed releases an internal lock so that the knurled delay setting knob may be rotated.

The M148 (T45E7) Adapter Booster (Figure 19) is used in conjunction with the M904E2 Mechanical Nose Fuze. Its overall length is 6.83 inches and the outside thread diameter is 3.5 inches. The inside diameter has a 2.0 inch thread to accommodate the Fuze M904E2. The purpose of this adapter booster is to mate the Fuze M904E2 with the Mk 80 series of bombs. It also serves to transmit the explosive train action of the fuze to the main charge of the bomb. The Adapter Booster contains approximately 180 grams of tetryl (doughnut shape) in its base and is covered with a steel closing cup.

The Mechanical Long Delay Tail Fuze Mk 346 Mod 0 is also used to a limited extent in the Mk 80 series of bombs and is of interest from a cook-off point of view. The Fuze Mk 346 is shown in Figure 20. It is approximately 5-3/8 inches long and is threaded for a two-inch adapter well. For purposes of description the term "outer" end and "base" end are used. The outer end couples to a fuze-tail drive shaft (Figure 21a). Because it is a tail fuze which is not mounted at the extreme end of the fin, the Mk 346 must be fitted with an arming assembly. The arming assembly consists of four basic components, Fuze Drive Mk 5, an adapter, drive shaft and a funnel guide. Figure 21b shows the complete arming assembly. The adapter in Figure 21b is affixed to the conical tail section by means of three socket-head set screws. The extension drive shaft couples the output spindle of the fuze drive to the input shaft of the fuze. The extension drive shaft therefore provides a direct heat path from the fire to the fuze. The funnel guide is a molded polyethylene sleeve which snaps over the outer end of the fuze. The




FIG. 17 M904E2 INSTALLED IN A MARK 80 SERIES BOMB





FIG. 18 MECHANICAL NOSE FUZE M904E2-SECTIONAL AND EXPLODED VIEWS







FIG. 19 ADAPTER BOOSTER 145E SERIES



TOTAL WEIGHT 4.4 LBS

## FIG. 20 MECHANICAL LING DELAY FUZE MARK 346 MOD 0




FIG. 21A FUZE DRIVE MARK 5 MOD 1

### NOLTR 71-124




FIG. 21 B TYPICAL ARMING ASSEMBLY




FIG. 22 ADAPTER BOOSTER T46 SERIES

base end of the fuze fits into an adapter booster well. The Adapter Booster T46 is installed into the bomb fuze well. It contains approximately 410 grams of tetryl. The overall length of the adapter booster is 8.7 inches. The outer thread diameter is 3.5 inches and the inside thread diameter is 2.0 inches to accomodate the Fuze Mk 346. The Adapter Booster T46 series is shown in Figure 22. The only explosive components integral to the fuze are a detonator and lead. It is unknown how these components react under intense heat.

## GENERAL PURPOSE 500-POUND MARK 82 BOMB

The Mark 82 Bomb has a cylindrical body with an ogival nose. A conical fin is attached to the aft end of the bomb body by set screws. The length of the assembled bomb is 86.90 inches. The fin span is 15.1 inches. The average weight of the explosive charge is 192 pounds and the weight of the assembled bomb is 531.0 pounds. The Mk 82 bomb is shown in Figure 23.

The tubes for the electric fuze cable harness connect the nose and tail cavities with the charging well between the lugs on the outer surface of the bomb. The electric fuze cable harness was removed in cook-off tests in order to provide space for thermocouples and probes. Two suspension lugs, spaced 14 inches apart, and a hoisting lug at the center of gravity were threaded into lug inserts on the bomb body. The bombs were hung in the burning pit by means of chains attached to the suspension lugs.

#### DEFINITION OF TERMS

The detonation of an explosive in air causes a relatively large amount of energy to be released in a short time. A shock, or blast wave is formed at the surface and propagates outward. This shock wave starts with an initial high pressure-high velocity near the explosive and eventually decays to a sound wave at some distance from the charge. In order to classify the type of reaction occurring it is usually necessary to obtain the air blast parameters such as peak pressure, time of reaction and the length of the duration of the shock front. In the cook-off experiments which will be described, air blast procedures were used when possible to classify the type of reaction occurring. Often times however, inert bombs and live fuzes were used and insufficient explosive was present to measure the air blast parameters. Because of the high temperatures surrounding the pit, close in measurements could not be made. The following definitions of reactions as promulgated by NAVORD Message 132244Z March 1969 were used in interpreting the violence of the cook-off event.

<u>Detonation</u>: Munition performs in design mode. Maximum possible air shock formed. Essentially all of case broken into small fragments. Blast and fragment damage is at maximum. Severity of blast causes maximum ground crater or flight deck hole capable by the warhead.

47 UNCLASSIFIED




FIG. 23 MK - 82 GENERAL PURPOSE BOMB

Partial Detonation: Only part of total explosive in munition detonates. Strong air shock and small as well as large case fragments produced. Small fragments are similar to those in normal munition detonation. Extensive blast and fragmentation damage to environment. Amount of damage and extent of breakup of case into small fragments increases with increasing amount of explosive that detonated. Severity of blast could cause large ground crater, or large flight deck hole on carrier if munition is large bomb; hole size depends on amount of explosive that detonates.

Explosion: Violent pressure rupture and fragmentation of munition case with resulting air shock. Most of metal case breaks into large pieces which are thrown about with unreacted or burning explosive. Some blast and fragmentation damage to environment. Fire and smoke damage. Severity of blast could cause minor ground crater, or small depression on flight deck of carrier if munition is large bomb.

<u>Deflagration</u>: Explosive in munition burns. Case may rupture or end plates blow out; however, no fragmentation of the case. No fragments are thrown about. Damage to environment due only to heat and smoke of fire. No discernable damage due to blast or fragmentation.

### EXPERIMENTAL RESULTS AND CONCLUSIONS

The first series of tests were performed to establish a baseline for an unprotected Nose Fuze M904E2 and Adapter Booster M148 (T45E7). A Tail Fuze Mk 346, Adapter Booster T46 and an arming assembly were also included in this test to ascertain their cook-off characteristics. Ionization probes were utilized to determine the site of the reaction. It was decided if the Tail Fuze Mk 346 Adapter Booster combination reacted first, they were to be eliminated from the program and investigated at a laber date following a solution to the Fuze M904E2 and M148 Adapter Booster combination. The Mk 346 Fuze and T46 Adapter Booster assembly therefore rode piggy-back to the Fuze M904E2 program.

The Mk 82 Bombs used during this series of tests were thermally protected bombs produced by NAD, Crane. The bomb casings were the regular production type and were insulated on the interior with ‡" of high melting hot melt. The exterior surface was protected with 15 mils of an intumescent paint manufactured by Cheesman Elliot and Company.

The ionization probes were 28 gauge chromel-alumel wire and were placed in the charging wells in six different locations. Eight thermocouple wires were placed symmetrically around the bomb to obtain the fire temperature. The bomb was suspended 36" above 2,500 gallons of JP-4 jet fuel in a 35' x 35' x 1' deep enclosure. The experimental set up is shown in Figure 24. The probe locations are shown in Figure 25. A wind velocity for firing of 3 knots or




FIG. 24 PHOTOGRAPH OF THERMALLY PROTECTED LIVE MK 82 BOMB OUTFITTED WITH MK 346 TAIL FUZE AND M-904E2 NOSE FUZE




FIG. 25 IONIZATION PROBE LOCATION IN MK 82 THERMALLY PROTECTED BOMB

less was generally observed. The fuel was initiated by means of four thermite grenades positioned at each end of the pit. The thermocouple data was recorded on paper tape and the probe data on magnetic tape.

### Puze Test No. 1

The first test of the Nose and Tail Fuze combination in an H-6 loaded and protected bomb gave a reaction five minutes and eighteen seconds (318 seconds) after the start of the fire. The average fire temperature was 1750°F and it burned for 16 minutes. Pin probe data indicated that the start of the reaction occurred in region 1, nearest to the M904E2 and M148 Adapter Booster. The bomb was blown into several large pieces and a slight overpressure was detected. Figure 26 shows a representative case fragment. The reaction was classified as an explosion.

## Fuze Test No. 2

In the next test the same configuration as above was exposed to the fuel fire. The atmospheric conditions were similar to the previous shot and the wind velocity was 1-2 knots. The average fire temperature was 1600°F. The ionization probes were located in the charging wells identical to Figure 25. A top view of the set-up is shown in Figure 27. Seven minutes and fifty-five seconds (475 seconds) after the start of the fire the bomb detonated. Small fragments were strewn about the area and a crater approximately eight feet in diameter and one foot deep was formed. A photograph of the area after the shot, Figure 28, shows the crater and case remnants of the detonation. Air blast over pressure measurements were also recorded. The close in gauge was driven off scale and the second gauge recorded a small overpressure. The over pressure measurement is shown in Figure 29. The steep initial pressure rise and the shape of the curve is indicative of a detonation. The average fire temperature in this run was lower than in the previous experiment which could account for the difference in cook-off times. The ionization probe data for this experiment indicated that the reaction initiated in the position where the tail fuze was located. As a result of this test the tail fuze investigations were set aside for future consideration.

## Puze Test No. 3

Another test was made with the same configuration as in Fuze Test No. 2 except the tail fuze and adapter booster were removed. The wind conditions were calm. Five minutes and forty-two seconds (342 seconds) after the start of the fire the bomb exploded. The nose of the bomb was blown 6 to 7 feet from the supporting stand. Small pieces of unburned explosive were found in the pit and at the surface. The bomb was essentially blown into 10 large fragments. Representative pieces of the bomb are shown in Figure 30. No probe data was taken in this shot. A small overpressure was observed with the close in air blast gauge. From the air blast curve



FIG. 26 REPRESENTATIVE CASE FRAGMENT FROM TEST FUZE NO. 1



FIG. 27 TOP VIEW OF THERMALLY PROTECTED LIVE MK 82 BOMB CONTAINING MK 346 TAIL FUZE AND M -904E2 NOSE FUZE-FUZE SHOT NO. 2



FIG. 28 CRATERING AND CASE REMNANTS OF FUZE TEST NO. 2




FIG. 29 ACTUAL AIR BLAST TRACE OF FUZE TEST NO 2






FIG. 30 BOMB FRAGMENTS FROM FUZE TEST NO. 3. TOP VIEW SHOWS TAIL SECTION. BOTTOM VIEW SHOWS AFT END OF BOMB.

## UNCLASSIFIED NOLTR 71-124

it appears as though two reactions were occurring. This is shown in Figure 31. The average fire temperature was 1650°F, similar to the fire temperature observed in Fuze Test No. 2. It appears from these results that the average cook-off time of an unprotected fuze in a thermally protected bomb is on the order of five minutes. It was immediately apparent that a fix would have to be applied to the fuze in order to extend its cook-off time and make it more compatible with the thermally protected bombs which were being tested at the Naval Weapons Laboratory, Dahlgren, Va. The thermally protected bombs proposed for ultimate Fleet issue will be coated externally with an insulation coating and internally with high melting hot melt. Cook-off times range from nine minutes to 15 minutes.

The results of Fuze Test No's. 1, 2 and 3 are tabulated in Table 17.

Since fuzes, particularly nose fuzes, cook-off first when tested in thermally protected bombs, it was decided to investigate the use of a rubber sleeve over the fuze body to delay cook-off. Candidate No. 1 sleeving was chosen because of (1) the small scale burn tests, (2) superior environmental characteristics, (3) its availability and (4) because of our familiarity with the material from previous bomb testing. From previous tests it was determined that the Candidate No. 1 sleeve must be bonded to the metal substrate to achieve maximum insulation. The adhesive which was found to be most effective was a Dow Corning Silicone Adhesive #737.

### Fuze Test No. 4

A Mk 82 Bomb internally coated with  $\frac{1}{4}$ " high melting hot melt was filled with Filler E which is an inert simulant for explosive. The Filler E loaded bomb was fitted with an inert T45E7 Adapter Booster and live Fuze M904E2 containing the Candidate No. 1 rubber cover bonded on with the Dow Corning Silicone Adhesive. The aluminum sleeve in the Adapter Booster was instrumented with four thermocouples, the Fuze M904E2 with four thermocouples and the inert adapter booster charge with four thermocouples. Eight thermocouples were positioned 90° around the major diameter of the bomb. The thermocouple arrangement is shown in Figure 32, for the adapter booster and in Figure 33 for the Fuze M904E2. No air blast measurements were made due to the small amount of explosive present and the inability to make close in measurements because of the intense heat generated by the fuel fire. The wind velocity was 0-1 knots measured in the pit at the bomb level. Eleven minutes and sixteen seconds (676 seconds) after the start of the fire the fuze appeared to detenate. The fuze was blown approximately 900 feet from the site of the reaction and the cup containing the tetryl in the Fuze M904E2 was blown completely apart. The fire temperature was approximately 1700° F and the fuze temperature approximately \$25° F before detonation. The fire burned for 15 minutes. The adapter booster temperature appeared to be approximately 350° F before the reaction. The thermocouple data is shown in Figure 34.

57 UNCLASSIFIED




FIG. 31 AIR BLAST CURVE OF FUZE TEST NO 3

Table 17

Summary of Cook-Off Results of Thermally Protected H-6 Loaded Mk 82 Bombs with Live Fuzes

Reaction Site	M904E2 Fuze	MK 346 Fuze	M904E2 Fuze
Avg. Fire Temp. °F	1750	1600	1650
Kind * of Reaction	M	A	M
Reaction Time Sec.	318	475	342
Tail Fuze Mk 346 Adapter Booster T4684	Live	Live	None
Nose Fuze M904E2 Adapter Booster T45E7	Live	Live	Live
Fuze Test No.	7	O)	ю

59 UNCLASSIFIED

D = Detonation E = Explosion




FIG. 32 THERMOCOUPLE ARRANGEMENT IN M148 (T45E7) ADAPTER BOOSTER




FIG. 33 THERMOCOUPLE ARRANGEMENT IN NOSE FUZE M 90 4E2




FIG. 34 TIME TEMPERATURE PLOT OF FUZE TEST NO 4

### Fuze Test No. 5

Another test was run in the same manner as in the previous shot. The fuze-bomb configuration was identical to Fuze Test No. 4. The wind velocity at the bomb level was 0-1 knot. Ten minutes and thirty-eight seconds (638 seconds) after the start of the fire the fuze detonated. The cup containing the tetryl was blown apart and the aluminum sleeve was also destroyed. The average fire temperature was 1700°F. The fire burned for 15 minutes and twanty seconds. The thermocouple registering the highest temperatures for the fuze, adapter booster and fire temperature are shown in Figure 35. The maximum difference between the four thermocouples was 50°F.

## Fuze Test No. 6

In order to ascertain the vulnerability of the Adapter Booster M148 (T45E7) a live Nose Fuze M904E2 was protected with Candidate No. 1 sleeve in an identical fashion to the two previous experiments. However, this time a live T45E7 unfixed Adapter Booster was used. An inert bomb with thigh melting hot melt liner, Filler E, and intumescent paint was again used as the test vehicle. Four thermocouples were again used in the adapter booster to detect the time and temperature of the reaction. Eight thermocouples were used to measure the outside fire temperature. The wind velocity was O-1 knot. Engulfment was complete. Six minutes and forty-seven seconds (407 seconds) after the start of the fire the adapter booster deflagrated expelling the Nose Fuze M904E2. The fuze was recovered intact. The aluminum sleeve was still intact in the bomb, although welded to the walls because of the intense heat of the burning explosive. Thermocouple data irdicated that the average fire temperature was 1650°F. The cook-off temperature of the adapter booster explosive was 375°F. The thermocouple record is shown in Figure 36. It was observed in this fuze test that Filler E appeared to contribute to the burning of the adapter booster, therefore, it was decided to discontinue using this simulant in future cook-off tests.

#### Fuze Test No. 7

Thus far fixed M904E2 Fuzes and unfixed live and inert M148 (T45E7) Adapter Boosters has been tested in inert bombs. The configuration for this test consisted of a live Fuze M904E2 outfitted with a Candidate No. 1 sleeve bonded onto the fuze body with Silicone Adhesive #737. The live fixed nose fuze was inserted into an unfixed Adapter Booster T45E7 and this in turn was installed into a live thermally fixed bomb containing E-6 explosive. The wind velocity in the pit was 0-3 knots, however, there were occasional gusts up to 5 knots. The average fire temperature was 1600°F shown in Figure 37. No thermocouples were installed into the fuze or bomb for this test. Eight minutes and fifty seconds (530 seconds) after the start of the fire the adapter booster reacted




FIG. 35 TIME TEMPERATURE PLOT OF FUZE TEST NO 5





FIG. 36 TIME TEMPERATURE PLOT OF FUZE TEST NO 6



## UNCLASSIFIED NOLTR 71-124

expelling the fuze, and leaving most of the fuze intact. Nine minutes and twenty seconds (560 seconds) after the start of the experiment the fire died out. At 11 minutes and 20 seconds or two minutes later the mass of the explosive in the bomb exploded splitting the case into several large fragments. This was observed on closed circuit television. It indicates that once a bomb has been heated in a fuel fire it is still subject to reaction even after the bomb is no longer engulfed in flame.

## Fuze Test No. 8

The same configuration was used as in Fuze Test No. 7. Eight outside thermocouples were used to record fire temperature. Four thermocouples were positioned in the bottom of the adapter booster well to record the booster action. The adapter booster thermocouple location is shown in Figure 38. Cook-off resulted 6 minutes and 24 seconds (384 seconds) after ignition of the fuel. The action resulted in adapter booster ignition and fuze ejection. The Fuze M904E2 was recovered intact approximately 100 yards from the pit. Ten minutes and sixteen seconds (616 seconds) after ignition the bomb deflagrated. The average fire temperature was 1650°F. This is shown in Figure 39. A photograph of the test set up is shown in Figure 40.

### Fuze Test No. 9

Fuze Test No. 9 was run in order to establish a baseline time for adapter booster cook-off. An inert Fuze M904E2 equipped with the Candidate No. 1 sleeve material bonded with Silastic 737 was inserted into a live T45E7 Adapter Booster. An inert sand filled thermally protected bomb was used as the test vehicle. The thermocouple arrangement was identical to those in the previous experiment. The average fire temperature in this experiment was 1575°F. A typical thermogram is shown in Figure 41. Seven minutes 28 seconds (448 seconds) after ignition of the fuel the adapter booster reacted. The resultant action was a partial detonation, destroying the adapter ring of the Adapter Booster and part of the fuze. This time, however, the front of the bomb was not peeled back as in other violent actions.

These results clearly establish that a material such as Candidate No. 1 sleeve when bonded properly onto a Fuze M904E2 will extend the cook-off time of the fuze. It also shows, however, that when this is accomplished the adapter booster becomes the weak link and must be thermally protected. The results of the tests using Candidate No. 1 sleeve is summarized in Table 18.

### Fuze Test No. 10

It was decided to explore the worth of a Neoprene sleeve in accordance with Federal Specification 22T-831, Amendment 2 on the Fuze M904E2. Neoprene tubing  $\frac{1}{4}$ " wall thickness was bonded to a live

67 UNCLASSIFIED




FIG. 38 THERMOCOUPLE LOCATION IN ADAPTER BOOSTER WELL - FUZE TEST NO. 8




FIG. 39 TIME TEMPERATURE PLOT OF FUZE TEST NO 8



FIG. 40 TEST SET UP FOR FUZE TEST NO.8




FIG. 41 TIME TEMPERATURE PLOT OF FUZE TEST NO 9

Table 18

Cook-Off Results on Fuze N904E2 Equipped with Candidate No. 1 Sleeve and Mounted in Thermally Protected MK 82 Bombs

Type of Reaction	Fuze Detonation	Same as above	Adapter Booster Deflagration	Adapter Booster Deflagration	Adapter Booster Deflagration	Adapter Booster Detonation
Reaction Time Sec.	919	638	407	590	384	844
Bomb Mk 82 Configuration	Inert Filler E Thermally Protected	Same as above	Same as above	Live Mk 82 Bomb thermally protected with H-6 explosive	Same as above	Inert Mk 82 Bomb Thermally protected with Intumescent Paint
T45E7 Inert Booster	Inert T4587	Same as above	Live T45E7	Same and above	Same as above	Live T4587
Nose Puze M904E2 Configuration	Live - Fixed with Candidate No. 1 Sleeve*	Same as above	Same as above	Same as above	Same as above	Inert - Fixed with Candidate No. 1 Sleeve
Fuze No.	at .	UNCLA	o 72 SSIFIE	<b>-</b>	ω	σ.

\*Bonded to Puze with Dow Corning 737 Adhesive.

# UNCLASSIFIED NOLTR 71-124

Fuze M904E2 by means of Silastic 737. This thermally protected fuze was installed in an inert T45E7 Adapter Booster and the entire assembly installed in a Mk 82 inert sand filled thermally protected bomb. The bomb was instrumented with thermocouples, as in our previous tests. Seven minutes twelve seconds (432 seconds) after ignition of the fuel the fuze reacted. The reaction was violent and can be classified as an explosion. The plots of temperature vs time for Fuze Test No. 10 is shown in Figure 42. This thermogram, as in other cases, represents the thermocouple which recorded the highest temperatures. The cook-off temperature of the fuze appears to be 470°F. The results of this test indicate that when intumescence capability is incorporated into a rubbery neoprene type material (such as Candidate No. 1) superior thermal insulating properties result. The military specification Neoprene material was therefore eliminated from future testing based on these results and laboratory screening.

### OPEN ADAPTER BOOSTER INVESTIGATIONS

As a result of the previous tests with live and inert Adapter Boosters, concern was expressed regarding the performance of the unprotected adapter booster when containing a thermally protected fuze. Even more concern was expressed when it was observed that operationally, unfuzed bombs, containing adapter boosters are brought to the flight deck without any cover on the adapter booster. Shortly before aircraft take off, the fuzes are installed into the bomb. It therefore became of interest to try and simulate a condition aboard ship where wind was blowing toward the nose of the bomb so the flames would lick into the open adapter booster cavity. Statistically, the probability of the wind blowing in the proper direction is high, since the aircraft are lined symmetrically around the fan tail. See Figure 43.

Fuze Tests No's. 11, 12, 13 and 14 were concerned with determining the vulnerability of the open adapter booster to flame impingment. These tests were run in a pit 28' x 28' x 1' deep.

#### Fuze Test No. 11

Two thermally protected, inert sand filled bombs were hung on one stand in the center of the pit. One bomb contained a live M148 Adapter Booster having the aluminum sleeve removed to ascertain if the removal of this highly conductive mass would influence the cook-off time. The second bomb contained a standard M148 Adapter Booster. The test was run in calm weather in order to ascertain the vulnerability of the adapter booster under calm wind conditions. The wind velocity was 0-3 knots in the pit and the atmospheric conditions were good. A photograph of the test set up is shown in Figure 44. Eleven minutes 43 seconds (703 seconds) after the start of the fire the adapter booster containing the aluminum sleeve deflagrated. Eighty-nine seconds later the adapter booster without the sleeve deflagrated. The reaction was extremely mild. See

73 UNCLASSIFIED




FIG. 42 TIME TEMPERATURE PLOT OF FUZE TEST NO. 10




FIG. 43 TYPICAL ARRANGEMENT OF AIRCRAFT ON FLIGHT DECK




FIG. 44 PHOTOGRAPH OF TEST SET UP OF FUZE TEST NO. 11

### UNCLASSIFIED NOLTR 71-124

Figure 45. From a review of 16mm motion pictures and the video tape replay it was evident that the flames did not impinge on the metal closing cup in the adapter booster cavity but they did flow over and around the open adapter booster. The fire temperature was 1600°F. The cook-off temperatures of both adapter boosters are plotted in Figure 46 together with the fire temperature. The long cook-off times of the unprotected open adapter booster suggest that the Fuze M904E2 is a strong contributor to the adapter booster problem by providing a heat path to the closing disc in the adapter booster cavity.

## Puze Test No. 12

Fuze Test No. 12 was designed to determine the vulnerability of the Adapter Booster M148 when flames were directed into the open The configuration was the same as in Fuze Test No. 11 (i.e., one Adapter Booster with sleeve and one without) except that the bombs were positioned in the direction in which the wind was blowing. The bombs were hung from a trapeze sort of arrangement which was designed so that the bombs could be moved in any direction based on the prevailing wind conditions, see Figure 47. Four thermocouples were placed symmetrically around each bomb to measure fire temperature. The bombs were suspended two feet above the fuel instead of three feet in order to ensure complete engulfment. The wind velocity was ten knots. After the fuel was ignited it was observed from the video tape replay that the fire was being directed into the booster cavity. Three minutes 46 seconds (226 seconds) later the adapter booster with the aluminum sleeve exploded. Fourteen seconds later the other adapter booster exploded. Both adapter boosters reacted quite violently destroying the aluminum sleeve and fragments were hurled toward the instrumentation bunker, see Figure 48. The time temperature plot for the adapter boosters and fire temperature are shown on Figure 49. Note the larger variation in fire temperature when the wind is blowing. The average deviation is much larger in these wind experiments.

## Fuze Test No. 13

Fuze Test No. 13 was designed to repeat Fuze Shot No. 11. Two thermally protected inert sand filled bombs containing live adapter boosters with and without the aluminum sleeving were positioned 26 inches above the level of the jet fuel. The wind was four knots. Four and one-half inches of fuel was placed in the pit. The thermite grenades were ignited and buildup was quite rapid. The average fire temperature was 1550°F. Time temperature plots and fire temperature are shown on Figure 50. Thirteen minutes 30 seconds (810 seconds) after ignition of the fuel the adapter booster without sleeve deflagrated vigorously. The reaction occurred just as the fire died out. Four minutes later the adapter booster containing the aluminum sleeve exploded splitting the bomb case open. Again we see that once an explosive item is heated in a fire and is no longer engulfed the danger of a violent reaction is still great.



FIG. 45 PHOTOGRAPH OF 1831 SHE AFTER FUZE 1831 NO.11




FIG. 46 TIME TEMPERATURE PLOT OF FUZE TEST NO 11




FIG.47 TEST SET UP BEFORE TEST MO, 12



HC.48 TEST SET UP AFTER FUZE TEST NO. 12





FIG. 49 TIME TEMPERATURE PLOT OF FUZE TEST NO 12



# UNCLASSIFIED NOLTR 71-124

From these three experiments it appears that in calm wind conditions the open adapter booster compares favorably with a fixed Fuze M904E2'in cook-off resistance. However, in strong wind conditions, when the flame is directed into the booster cavity the cook-off times are relatively short, and the adapter booster must be fixed.

### Puze Test No. 14

The top, bottom and inner surface of one of the aluminum sleeves of the M148 Adapter Booster were coated with intumescent paint in addition to the top of the closing disc and the face of the adapter ring. This was assembled into an inert loaded bomb and tested in a fire with a companion bomb containing a standard M145 Adapter Booster. It was hoped that when the flame impinged on the inner surface of the adapter booster, the paint would intumesce and thereby retard the heat transfer to the adapter booster explosive. The wind velocity was ten knots. The grenades were ignited, the wind shifted 180° in direction and the flame was not directed into the open adapter booster. As a result, the standard adapter booster deflagrated in twelve minutes fifteen seconds (735 seconds). The fixed adapter booster deflagrated in thirteen minutes forty-five seconds (825 seconds). The time temperature curves of this test are shown in Figure 51.

Due to the uncertainity in conducting wind tests in this manner. it was decided to conduct the test utilizing a wind generator whereby both the wind velocity and direction could be carefully controlled. A three hundred horsepower electric motor with a variable pitch propeller blade was used (Figure 52). The motor was driven by a portable generator, see Figure 53, capable of delivering 1000 amperes for short intervals. A great deal of current was initially needed to start the engine. Once the engine was in operation, the current dropped to approximately 100 Amperes. study was then made to determine the air flow patterns at different heights and distances from the center line of the propeller. Figure 54 shows the results of this study. The ordinate of the plot indicates the vertical distance along the center line of the propeller in feet. The abscissa represents the air velocity in miles per hour. A family of curves are shown in the figure ranging from distances of 20 ft to 50 ft. Due to the nature of the open adapter booster test and the hazards associated with the test set-up, it was decided to place the wind generator fifty feet from the test pit.

An experimental thermocouple grid shown in Figure 55 was then set up in order to determine the proper height the bombs should be positioned above the fuel level in order to get maximum temperatures. The results of this test are shown in Figures 56, 57, 58, 59 and 60. From the temperature time plots it was determined that the bombs should be positioned one foot above the level of the burning fuel to achieve the highest temperatures. The computer




FIG. ST TIME TEMPERATURE PLOT OF FUZE TEST NO 14




FIG. 52 WIND GENEPATOR



OC. 53 POWER GINERATOR





FIG. 54 AIR FLOW PATTERNS FOR 300 H. P. WIND GENERATOR

FIG. 55 EXPERIMENTAL THERMOCOUPLE GRID FCR DETERMINING HOTTEST POINT IN FIRE








FIG. 56 TIME TEMPERATURE CURVE OF THERMOCOUPLE POSITIONED ONE FOOT ABOVE FUEL LEVEL




FIG. 59 TIME TEMPERATURE CURVE OF THERMOCOUPLE POSITIONED FOUR FEET ABOVE FUEL LEVEL




FIG. 58 TIME TEMPERATURE CURVE OF THERMOCOUPLE POSITIONED THREE FEET ABOVE FUEL LEVEL




FIG. 60 TIME TEMPERATURE CURVE OF THERMOCOUPLE POSITIONED FIVE FEET ABOVE FUEL LEVEL

# UNCLASSIFIED NOLTR 71-124


plots shown in the above figures were made possible at this stage in the program by coupling an incremental tape recorder (magnetic tape) with the data acquisition system. The program for the plot routine is shown in Appendix B.

### Fuze Test No. 15


Fuze tests 15 and 16 were performed with the air of the wind generator. Fuze Test No. 15 consisted of suspending two inert concrete filled thermally protected bombs outfitted identically with live adapter boosters. The adapter boosters were both thermally fixed in the following manner. The inner surface and top surface of the aluminum sleeve were coated with 30 mils of an NOL formulated intumescent paint called Insunol (See NAVAIR Dwg. No. 599AS105). Four mils of a polyurethane overcoat were used to seal the paint. A steel disc 2.50" in outside diameter and 29 mils thick was painted on both sides with a 30 mil thickness of intumescent paint and the The face of the adapter ring was also painted with 30 mils of intumescent paint and a 4 mil overcoat. The steel disc with the intumescent paint was placed on top of the closing disc of the adapter booster, the painted aluminum sleeve reinserted and held in a place with the painted adapter ring. A parts arrangement of an Adapter Booster M148 incorporating the intumescent paint fixes is shown on Figure 61. The coating of the steel adapter ring vith the intumescent paint was done to retard the heat transfer to the booster of the Fuze M904E2. It was hoped, however, that the intumescent paint would also extend the cook-off times of the adapter booster. Two identical Mk 82 Bombs vere suspended one foot above the surface of the fuel level; they were placed at the extreme end of the pit facing the wind generator. Figure 62 shows the experimental set up. Eight thermocouples were installed in each Four thermocouples were placed at the interface of the tetryl and felt disc, and four were placed in the booster adapter ring hole. Four thermocouples were symmetrically placed around each bomb to record fire temperature. Seven inches of fuel (JP-4) on top of one inch of water was placed in the pit. The wind velocity was measured at 24 knots at the level of the adapter booster. fire burned after ignition for 18 minutes (1080 seconds) and then went out. Two hundred fifty-two seconds later one of the adapter boosters deflagrated. Two hundred eighty-six seconds later the second bomb deflagrated. The temperature profiles of the thermocouples in contact with the explosive are shown in Figures 63 and 64. The fire temperature thermocouple is shown in Figure 65. The recorder was shut after 1360 seconds. The fire temperatures are consistent with the temperatures determined in the calibration shot. The flames were directed into the booster cavity as determined by visual observations and 16mm color films.


# Fuze Test No. 16

Fuze Test No. 16 was set up to test an alternate fix if the intumescent paint fix failed on environmental storage or if an



FIC. 61. PAPT, AREAT CEREBLE 13: MATAR ADAPTER BOOKTER MODIFIED TO INCORPORATE INTUMESCENT PAINT FIX










FIG. 63 TIME TEMPERATURE CURVE FOR FUZE TEST NO. 15




FIG. 65 PROFILE OF FIRE TEMPERATURE FOR FUZE TEST NO. 15

### UNCLASSIFIED NOLTR 71-124

incompatibility with the fuze fix developed.

There were a number of proposed approaches in addition to intumescent paint to increase the cook-off time of the open adapter booster. These are listed below:

- 1. Insulative disc and washer
- 2. Spring and cup
- 3. Phenolic fuze liner
- 4. Heat resistant cover

These various ideas were actually represented by hardware for further consideration, with a phenolic disc and washer being the first choice for further test. However, before any tests could be accomplished we were directed by the Naval Missile Center, as program manager, to test a .1" thickness of disc and washer of Candidate No.10 at the exclusion of all others. Figure 66 is a photograph of the disc and washer. The dimensions of the disc are 2.50" in outside diameter and .100" thick and it goes on top of the steel closing disc. The washer is 2.625" 0.D. x 1.625" I.D. x .100" thick and it goes between the adapter ring and sleeve. The sleeve was machined to a height of 2.903" to accomodate this increased thickness of material.

Two thermally protected inert concrete loaded bombs were fitted with thermally fixed live adapter boosters containing the Candidate No. 10 disc and washer. The bombs were suspended one foot above seven inches of the JP-4 fuel. The wind generator was turned on and the wind velocity was measured as 32 knots of which twenty knots was from the wind generator and 12 knots from natural wind which was blowing in the westerly direction.

Seventeen minutes and twenty seconds (1040 seconds) after the start of the fire the first bomb detonated. The nose of the bomb was bulged out and expanded, (see Figure 67). The aluminum sleeve was destroyed. At 20 minutes and 42 seconds (1242 seconds), or 202 seconds later, the second bomb deflagrated. The fire temperature thermogram is shown in Figure 68. Again, the average fire temperature is compatible with what we find in the calibration shot. The time temperature response of the thermocouples in contact with the explosive are shown in Figures 69 and 70. We see a flat spot on the thermogram of the thermocouples in contact with the explosive. This indicates that the Candidate No. 10 material may be evolving water keeping the explosive relatively cool. The results of the open booster tests are summarized in Table 19.


From an analysis of the preceding data, both the intumescent paint and the Candidate No. 10 material appear to be thermally acceptable as a fix for the open adapter booster. The intumescent paint, however, was chosen as the primary fix because of the cheap material costs and its easy application. Since only one adapter

98 Unclassified





FIG. 67 PHOTOGRAPH OF AREA AFTER FUZE 1EST NO.16








FIG. 68 FIRE TEMPERATURE THEMOGRAM OF FUZE TEST NO. 16




FIG. 70 MI48 ADAPTER BOOSTER THERMOGRAM OF FUZE TEST NO. 16

Table 19

Cook-Off Results on M148 (T45E7) Open Adapter Boosters Mounted in Thermally Protected Mk 82 Bombs

NOLTH (1-124										
Conditions	0-3 knots	0-3 knots	10 knots in cavity	10 knots in cavity	4 knots	4 knots	10 knots (wind shifted)	10 knots (wind shifted)		
Aind of Heaction	Deflagration	Deflagration	Explosion	Explosion	Explosion	Explosion	Deflagration n	Deflagration n		
Time/sec.	703	792	226	240	810 (Fire died out in 810 sec.)	1050 (Fire died out in 810 sec.)	825 (Fire direction changed)	735 (Fire direction changed)		
Corrents	Sand Filled	Ξ	=	# #	±	<u>=</u>	r r	E		
Booster configuration	Live - with aluminum sleeve	Live - without aluminum sleeve	Live - with aluminum sigeve. Suspended 24 in. above fuel.	Live - Without aluminum sleeve, Suspended 24 in. above fuel.	Live - with aluminum sleeve. Suspended 26 in. above fuel.	Live - Without aluminum sleeve. Suspended 26 in. above fuel.	Live - painted inside and face with Insunol.	Live - painted inside and face with Insunol		
CN	r r	11	C	(V rd	4	8	14	14		
UNCLASSIFIED										
	booster configuration contents time/sec. Aind of heaction	Live - with aluminum Sand Filled 703 Deflagration sleeve	Live - without aluminum "" " 792 Deflagration sleeve	11 Live - with aluminum " " 792 Deflagration 0-3 knots in sleeve 12 Live - with aluminum " " " 226 Explosion cavity above fuel.	11 Live - With aluminum Sand Filled 703 Deflagration 0-3 knots sleeve 11 Live - With aluminum " " 792 Deflagration 0-3 knots is sleeve 12 Live - With aluminum " " 226 Explosion cavity above fuel.  12 Live - Without aluminum " " 240 Explosion cavity cavity above fuel.	11 Live - with aluminum Sand Filled 703 Deflagration C-3 knots sleeve 12 Live - with aluminum " " 792 Deflagration C-3 knots in sleeve Suspended 24 in. " 240 Explosion Cavity above fuel.  12 Live - with aluminum " " 240 Explosion Cavity above fuel.  13 Live - with aluminum " " 240 Explosion Cavity above fuel.  14 Live - with aluminum " " 240 Explosion Cavity above fuel.  15 Live - with aluminum " " 240 Explosion Cavity above fuel.  16 Live - with aluminum " " 810 Explosion 4 knots in Cavity above fuel.	11 Live - With aluminum Sand Filled 703 Deflagration C-3 knots sleeve  12 Live - Without aluminum sleeve labeled 26 in sleeve labove fuel.  13 Live - Without aluminum sleeve labove fuel.  14 Live - Without aluminum sleeve labove fuel.  15 Live - Without aluminum sleeve labove fuel.  16 Live - Without aluminum sleeve labove fuel.  1792 Deflagration C-3 knots in cavity above fuel.  18 Live - Without aluminum sleeve labove fuel.  19 Live - Without aluminum sleeve labove fuel.  1050 Explosion sleeve labove fuel.  11 Live - Without aluminum sleeve labove fuel.  12 Live - Without aluminum sleeve labove fuel.  13 Live - Without aluminum sleeve labove fuel.  14 knots above fuel.  15 Live - Without aluminum sleeve labove fuel.  16 Rive died out above fuel.  1792 Deflagration constitutions sleeve labove fuel.  18 Live - Without aluminum sleeve labove fuel.  19 Live - Without aluminum sleeve labove fuel.  10 Knots in cavity sleeve labove fuel.  11 Live - Without aluminum sleeve labove fuel.  12 Live - Without aluminum sleeve labove fuel.  18 Live - Without aluminum sleeve labove fuel.	11   Live - with aluminum   "   792   Deflagration   C-3 knots     12   Live - with aluminum   "   792   Deflagration   C-3 knots     13   Live - with aluminum   "   226   Explosion   C-3 knots in cavity     14   Live - with utaluminum   "   810   Explosion   4 knots in cavity     15   Live - with aluminum   "   810   Explosion   4 knots in cavity     16   Live - with aluminum   "   810   Explosion   4 knots in cavity     17   Live - with aluminum   "   810   Explosion   4 knots in cavity     18   Live - with aluminum   "   810   Explosion   4 knots     19   Live - with aluminum   "   810   Explosion   4 knots     10   Live - with aluminum   "   825   Explosion   4 knots     11   Live - painted Inaide   "   825   Deflagration   Mind shifted     12   Live - painted Inaide   "   825   Deflagration   Mind shifted     12   Live - painted Inaide   "   825   Deflagration   Mind shifted     14   Live - painted Inaide   "   825   Deflagration   Mind shifted     15   Live - painted Inaide   "   825   Deflagration   Mind shifted     15   Live - painted Inaide   "   825   Deflagration     16   Live - painted Inaide   "   825   Deflagration     17   Live - painted Inaide   "   825   Deflagration     18   Live - painted Inaide   "   825   Deflagration     19   Live - painted Inaide   "   825   Deflagration     10   Mind shifted     10   Mind shifted   Mind shifted   Mind shifted     10   Mind shifted   Min		

Table 19 (Con't.)

Does Adapter  Booster Configuration  Live - painted inside and disc and face with  Live - painted face and disc and washer  Same as above  Live - painted face and disc and washer  Same as above  "   151   154   104	Reaction Wind of Reaction Conditions	1332 Deflagration 24 knots (Fire died out in 1080 sec.)	1518 Deflagration 24 knots (Fire died out in 1080 sec.)	0 Detenation 32 knots (**Ind generator*)	Deflagration 32 knots (wind generator)	
Adapter  - painted inside disc and face wit nol.  - painted face disc and washer as above				1040	u 1245	
EM HAH W HA W	Lguration	1de With	ame as above	lve - painted face nd disc and washer	8	
UNCLASSIFIE				\O FI	က် 104	

# UNCLASSIFIED NOLTR 71-124

booster fix was to be evaluated the final choice was to be based on a combined test with the thermally protected Fuze M904E2. This combined fix would determine if the fuze was compatible with the adapter booster fix.

In order to obtain the most effective Nose Fuze M904E2 protective covering the best insulators from the small scale fire tests were fabricated into protective sleeves. The castable sleeves were fabricated by using two piece aluminum molds shown in Figures 71 and 72. The center core was fabricated out of Teflon in order to act as a mold release. The entire assembly was also sprayed with teflon mold release agent to facilitate easy removal from the molds. A jig was also made so that the holes for the window, screw and spring release of the Fuze M904E2 could be drilled in the proper place. This jig is shown in Figure 73.

## Fuze Test No. 17

Based on experience gained on cook-off testing and in the interest of obtaining more information for each fire, at less cost per bomb, it was proposed to test four bombs in each fire. Such a plan was possible because of the ability through data acquisition equipment to determine the origin of reaction and information from a large number of sensors. Fuze Test No. 17 consisted of four inert sand filled bombs containing the high melting hot melt but not painted on the exterior surface with intumescent paint. All the adapter boosters were sand filled and inert. Three bombs contained live fixed Fuzes M904E2 and one bomb contained an inert unfixed Fuze M904E2 which served as a reference calorimeter. The live nose fuzes were equipped with sleeves fabricated out of Candidates No. 14, No. 8, and No. 1 materials. These sleeves were bonded on the fuze with Silastic 737.

Unfortunately, a different insulation procured for the protection of the thermocouples coming out of the bombs and into the reference junction was inadequate. Although 1000°F thermocouple wire was used the thermocouples shorted out after three minutes engulfment in the fire. It was therefore impossible to ascertain which shot cooked-off and when and only the total cook-off times as determined from the sound of reactions were obtained.

Six minutes (360 seconds) after the start of the fire the first fuze deflagrated. One hundred twenty seconds later the second fuze deflagrated and sixty seconds later the third fuze deflagrated. From inductive reasoning it is believed that the bomb outfitted with the fuze with Candidate No. 14 sleeve went in 360 seconds, the Candidate No. 8 material reacting next in 460 seconds and Candidate No. 1 material in 540 seconds. The shorter cook-off times of the Candidate No. 1 material, than was experienced previously, (see Table 18), was attributed to heat transfer through the front and sides of the thermally unprotected bombs. Therefore all future experiments were performed with thermally protected bombs fixed on the exterior with intumescent paint and the interior with high




FIG. 71 MOLD NO. 1 FOR PROTECTIVE FUZE COVERING



115.72 MOLDING, 210s PROTECTUR HUZE COVERING



IG. 23 JIG FOR DRILLING HOLFS IN PROTECTIVE COVERING

# UNCLASSIFIED NOLTR 71-124

melting hot melt.

### Fuze Test No. 18

Three of the next best insulators chosen from the small scale tests were fabricated into protective sleeves. The materials chosen for study were Candidates No. 12, Candidate No. 4 and Candidate No. 7. Candidate No. 12 and No. 4 were prepared by a contractor. Candidate No. 7 was procured, cast into a mold and cured at 80°C for one half hour at NOL.


Four thermally protected inert sand filled bombs were suspended three feet above the fuel level as in our previous tests. All bombs contained inert T45E7 Adapter Boosters. Three of the M904E2 Fuzes were fitted with one each of the sleeves and served as our reference calorimeter. The test arrangement is shown on Figure 74. The thermocouple arrangement was the same as in previous tests. In order to simplify the data presentation typical time temperature plots for each nose fuze and adapter booster will be presented.

The fuze outfitted with Candidate No. 12 was the first to cookoff. It deflagrated in nine minutes (540 seconds). Two hundred
sixteen seconds later the fuze prepared with the Candidate No. 4
deflagrated. One hundred ninety-two seconds later the fuze prepared
with Candidate No. 7 deflagrated mildly. Representative fuze
thermograms for each of the fixes are shown in Figure 75. It is
to be noted that the cook-off temperature of the fuze is approximately
400°F independent of the protective device on the fuze. Representative
thermocouple data are shown for the adapter booster in Figure 76.
The intumescent paint on the surface of the adapter booster appeared
to be effective in preventing heat from entering the front of the
bomb.

Subsequent to this test, the environmental storage tests indicated that the above materials would not survive environmental handling. Therefore Candidates No. 12, No. 4 and No. 7 were disregarded from any future consideration.

#### Fuze Test No. 19

Fuze Test No. 19 was similar to Fuze Test No. 17. The four materials tested were Candidates No. 14, No. 8, No. 1 and No. 5. All the bombs contained inert T45E7 Adapter Boosters. All the bombs were thermally protected. Three had live fuzes protected with Candidates No. 14, No. 8 and No. 1. The other was an inert fuze protected with Candidate No. 5 material that was included at the request of the NMC, Pt. Mugu representative. The bombs were suspended three feet above 2200 gallons of JP-4 jet fuel and ignited by means of thermite grenades. All of the fuzes deflagrated mildly. The fuze with Candidate No. 14 sleeve deflagrated in eight minutes fifty seconds (530 seconds). The fuze with Candidate No. 8 sleeve deflagrated in eight minutes fifty-eight seconds (538 seconds) and






FIG. 75 THERMOGRAMS OF FUZE THERMOCOUPLES FOR FUZE TEST FUC 18




FIG. 76 THERMOGRAMS OF ADAPTER BOCKSTE THERMOCOUPLES FOR HIZE TEST NO 18

# UNCLASSIFIED NOLTR 71-124

the fuze with Candidate No. 1 sleeve cooked-off in nine minutes fifty-eight seconds (598 seconds). It was estimated that had the fuze with Candidate No. 5 sleeve been loaded cook-off would have occurred in nine minutes fifty seconds (590 seconds). The fire temperature plot and fuze plots are shown in Figure 77. The temperatures on the Adapter Booster thermocouples are shown on Figure 78. From these data it is also observed that the fuze protective covering influences the heat transfer to the booster. Because of the poor results of environmental screening of Candidate No. 8 and cost it was eliminated from any future consideration. Candidates No. 14, attractive from a cost point, and Candidate No. 5 were retained for further testing.

### Fuze Test No. 20

Four sleeve materials consisting of Candidates No. 5, No. 10, No. 1 and No. 14 were employed in this test. The configurations are shown in Figures 79 and 80. Candidate No. 5 sleeve was fabricated with a lip to cover the face of the adapter ring on the adapter booster. A washer of Candidate No. 1 material (same thickness as sleeve) was cemented to the adapter ring face for test in conjunction with Candidate No. 1 material on the Fuze M904E2. A similar arrangement was made up with Candidate No. 10 material. Candidate No. 14 sleeve has a contour similar to a fuze on an existing Navy weapon. The heavy wall is judged to be necessary for the material to meet the insulation requirements and the projected relatively low material costs makes this choice possible. The base diameter of the truncated cone conforms to the diameter of the bomb at the juncture. The four live Fuzes M904E2 with the above sleeves were assembled into Inert M148 Adapter Boosters and Mk 82 sand filled thermally protected bombs. The Fuze M904E2 with Candidate No. 5 deflagrated in nine minutes twenty seconds (560 seconds), see Figure 81. The fuze with Candidate No. 1 deflagrated in twelve minutes forty seconds (760 seconds), see Figure 72. The fuze with Candidate No. 14 deflagrated in thirteen minutes (780 seconds), see Figure 83. The fuze with Candidate No. 10 sleeve and washer deflagrated in twelve minutes forty seconds (760 seconds), see Figure 84. The Adapter Booster thermograms are shown in Figures 85-88. The fire temperature thermogram is shown in Figure 89. All of the cook-off's resulted in deflagrations. The bombs were completely intact after the fire. Photographs of the set up and a view after the fire are shown in Figures 90 and 91.

### Fuze Test No. 21

Fuze Test No. 21 was a repeat of Fuze Test No. 20. The washers prepared from Candidate No. 1 and No. 10 were secured to the Adapter Booster ring face with RTV 737 adhesive.

The fuze protected with the Candidate No. 5 deflagrated in seven minutes twenty seconds (440 seconds). The fuze with Candidate No. 1 deflagrated in twelve minutes (720 seconds). The fuze with Candidate No. 10 sleeve deflagrated in seventeen minutes twenty seconds (1040 seconds) and the fuze with Candidate No. 14 deflagrated




FIG. 37 THE PANCE AM OF THE RACCOUPLES FOR FUZE TEST NO 19




FIG. 78 THERMOGRAMS OF ADAPTER BOOSTER THERMOCOUPLES FOR SHOT NO 19




FIG. 79 SCHEMATIC OF CANDIDATE NO 1, NO 10, NO 5 AND NO 14 SLEEVE




FIG. 80 PHOTOGRAPH OF SLEEVE CANDIDATE NO.1, NO.5, MODIFIED NO.10, AND NO.14




FIG. 82 THERMOGRAM OF FUZE TEST NO. 20 WITH CANDIDATE NO. 1 SLEEVE AND ADAPTER BOOSTER WASHER







FIG. 81 THERMOGRAM OF FUZE TEST NO. 20 WITH CANDIDATE NO. 5 SLEEVE










THERMOGRAM OF ADAPTER BOOSTER THERMOCOUPLE IN FUZE TEST NO. 20 WITH CANDIDATE NO. 14 SLEEVE ON M994E2 FUZE FIG. 86 THERMOGRAM OF ADAPTER BOOSTER THERMOCOUPLE IN FUZE TEST NO. 20 WITH CANDIDATE NO. 5 SLEEVE ON M904E2 FUZE FIG. 85








FIG. 87 THERMOGRAM OF ADAPTER BOOSTER THERMOCOUPLE IN FUZE TEST NO. 20 WITH CANDIDATE NO. 1 SLEEVE ON M904E2 FUZE AND WASHER ON ADAPTER






FIG. 89 THERMOGRAM OF FIRE TEMPERATURE THERMOCOUPLE FOR FUZE TEST NO. 20





124

#### UNCLASSIFIED NOLTR -71-124

in twenty minutes fifty-three seconds (1253 seconds). Six and one-half inches of fuel were used in the fire test. The fire burned for 1100 seconds. The fuze with Candidate No. 14 sleeve cooked-off after the fire was going out. Representative thermograms for each of the fuzes and adapter boosters are shown in Figures 92 through 97. Typical fire temperature thermograms are shown in Figure 98. The average fire temperature was 1660°F. Based on the cook-off times obtained in Fuze Tests No. 20 and 21, Candidate No. 5 was eliminated.

### Fuze Test No. 22

Fuze Test No. 22 was conducted in order to build the confidence level of the three best fuze fixes tested to date, and to determine the vulnerability of the adapter booster with a fixed fuze.

As before, four inert sand filled thermally protected bombs were tested. One live Fuze M904E2 was protected with a sleeve of Candidate No. 10 material and a washer of Candidate No. 1 material was cemented to the adapter ring. The second live fuze was protected with a Candidate No. 1 sleeve and a Candidate No. 1 washer on the adapter ring. The third live fuze was protected with a Candidate No. 14 sleeve. These fuzes were assembled in inert M148 Adapter Boosters. The fourth fuze was inert and protected with a Candidate No. 14 sleeve and was assembled into a live M148 (T45E7) Adapter Booster.

Eight minutes twenty seconds (500 seconds) after the start of the fire the fuze on the bomb equipped with the Candidate No. 14 sleeve and live M148 Adapter Booster deflagrated.

The fuze with Candidate No. 1 sleeve deflagrated in fourteen minutes thirty seconds (370 seconds). The fuze with Candidate No. 14 deflagrated in sixteen minutes forty seconds (1000 seconds) and the fuze with Candidate No. 10 sleeve deflagrated in twenty minutes thirty-five seconds (1235 seconds). The fire laster 18 minutes and 20 seconds so the fuze with the Candidate No. 10 sleeve reacted after the flame subsided. The reactions were quite mild even after slow cook-off. Figure 99 is a thermogram of the fire temperature. Figures 100-107 are thermograms of thermocouple data. It is interesting to note again that even after the fire is out the explosive continues to self heat until the ignition point is reached.


The data on this section of the fuze program is summarized in Table 20.

As a result of the preceding tests, the choice for a protective covering was narrowed from a field of fifteen candidates to three. The most promising were (1) Candidate No. 1, (2) Candidate No. 14 and (3) Candidate No. 10.

The following fire tests were designed to uncover any deficiencies in the insulative properties of the sleeve, and to

125

UNCLASSIFIED











FIG. 92 FUZE TEST NO. 21 - THERMOGRAM OF M904E2 FUZE PROTECTED WITH CANDIDATE NO. 5 SLEEVE





FUZE TEST NO. 21 - THERMOGRAM OF FUZE PROTECTED WITH THE CANDIDATE NO. 14 SLEEVE









FIG. 96 FUZE TEST NO. 21 THERMOGRAM ON INERT M148 ADAPTER BOOSTER THERMOCOUPLE WITH LIVE M904E2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE AND WASHER







FIG. 98 FUZE TEST NO. 21 THERMOGRAM OF FIRE TEMPERATURE THERMOCOUPLE







FIG. 100 FUZE TEST NO. 22 THERMOGRAM OF INERT M904E2 FUZE PROTECTED WITH CANDIDATE NO.14 SLEEVE








FIG. 102 FUZE TEST NO. 22 THERMOGRAM OF LIVE M904E2 FUZE PROTECTED WITH A CANDIDATE NO. 1 SLEEVE




FIG. 105 FUZE TEST NO. 22 THERMOGRAM OF INERT M148 ADAPTER BOOSTER - WITH LIVE M904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE




FIG. 104 FUZE TEST NO. 22 THERMOGRAM OF LIVE M904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE




FIG. 107 FUZE TEST NO. 22 THERMOGRAM OF AN INERT M148 ADAPTER BOOSTER WITH LIVE M904C2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE




FIG. 106 FUZE TEST NO. 22 THERMOGRAM OF A LIVE M904E2 FUZE PROTECTED WITH CANDIDATE NO.10 SLEEVE

Cook-Off Results on Nose Fuze M90452 Equipped with Various Protective Cook-Off Results on Nose Fuze M90452 Equipped with Fry 737 Table 20

Kind of Reaction	Deflagration	Deflagration	Deflagrations	Deflagration 11-154	Deflagration	Deflagration	Deflagration	Deflagration	Deflagration
Reaction Time Sec.	360*	480*	540*	075	756	846	530	598	538
Adapter Booster Configuration	Inert-sand filled.	Same as above	Same as above	Inert-sand filled.	Same as above	Same as above	Same as above	Same as above	Same as above
Nose Fuze M904E2 Configuration	Live with \hatangeright" Candidate No. 14	Live with t" Candidate No. 8	Live with t" Candidate No. 1 Sleeve	Live with the Candidate No. 12 Sleeve	Live with Candidate No. 4	Live with Candidate No. 7	Live with &" Candidate No. 14 Sleeve	Live with &"Candidate No. 1	Live with 4" Candidate No. 8 Sleeve
Mc 82 Bomb Configuration	Inert-sand filled with	Same as above	Same as above	Inert-sand filled with t" High Welting Hot Melt and Intumescent Paint on Adapter Ring and on Bomb	Same as above	Same as above	Same as above	Same as above	Same as above
Fuze Test	17	17	17	8 134	18	18	19	19	19

UNCLASSIFIED NOLTR 71-124								
Kind of Reaction	Deflagration	Deflagration	Defiagration	Deflagration	Deflagration	Derregranton		nor regration
Reaction Time Sec.	260	160	760	780	Oh प	720	1040	1100
Adapter Doster Configuration	Inert-sand filled	Same as above	Same as above	Same as above	Same as above	Same as above	Same as above	Same as above
Nose Puze M904E2 Configuration	Live with Candidate No. 5 covering front of bomb.	Live with Candidate No. 1 sleave extended 1" with grooves cut in end to fit over front of bomb.	Live with Camdidate No. 10 t aleeve and Candidate No. 1 dise on adapter ring.	Live with Candidate No. 14 sleeve to conform to shape of bomb.	Live with Candidate No. 5 covering front of bomb.	Live with Candidate No. 1 washer on adapter ring.	Live with Candidate No. 10 & Candidate No. 1 disc on adapter booster.	Live with Candidate No. 14 sleeve made to conform to shape of bomb.
MK 82 Bomb Configuration	Thermally protected bomb. No paint on adapter ring.	Same as above	Same as above	Same as above	Same as above	Same as above	Same as above	Same as above
Fuze Fest	20	50	R und	2 135 LASSIFIE	73 E	ช	23	ส

Table 20 (Con't.)

Test No.	Mk 82 Bomb Configuration	Nose Fuze M90422 Configuration	Adapter Booster Configuration	Time Sec.	of Reaction
55	Thermally protected bomb. No paint on adapter ring.	Live with Candidate No. 1 sleeve and washer of Candidate No. 1.	Inert-sand filled	870	Deflagration
22	Same as above	Live with Candidate No. 10 sleeve and washer of Candidate No. 1.	Same as above	1235**	Deflagration
NO UNCLA	Same as above	Live with Candidate No. 14 sleeve to conform to shape of bomb.	Same as above	1000	Deflagration
ଧ 136 SSIFTED	Same as above	Inert with Cendidate No 14 Sieeve made to conform to shape of bomb.	Live T45E7	200	Derlagration

UNCLASSIFIED NOLTR 71-124

Times to cook-off \* Thermocouples shorted out because of improper insulation. obtained from reaction sounds.

<sup>\*\*</sup> Fire lasted 1100 seconds.

build up the confidence level of the fixes. Ultimately, one material would be chosen as a back-up in case any deficiencies were uncovered in the evaluation phase of the program.

Concrete loaded Mk 82 Bombs were used in this phase of the program. These bombs were readily available, and served as a reasonably good simulant for the explosive. The bombs were painted on the exterior with intumescent paint and are referred to as thermally protected bombs.

### Fuze Test No. 23

In previous discussions, both a washer and intumescent paint were used on the exterior of the adapter ring. Fuze Test No. 23 was accomplished to select the paint or the washer as an adapter ring fix. The paint was shown to be effective previously in the open adapter booster fixes.

Four thermally protected Mk 82 Bombs were used as in our previous tests. Two of the bombs contained live Fuzes M904E2 and inert M148 Adapter Boosters and two contained inert Fuzes M904E2 and live M148 Adapter Boosters. All of the fuzes were protected with Candidate No. 1 sleeves. One of the live M148 Adapter Boosters contained a washer cemented to the adapter ring with RTV 737. The other was coated with intumescent paint. The inert adapter booster rings were equipped in a similar fashion.

The instrumentation of the fuzes both live and inert was similar to those in previous tests. Four thermocouples were placed symmetrically around the fuze in the same horizontal plane at the center of the delay element. The adapter boosters were instrumented by placing four thermocouples in contact with tetryl in the adapter booster. This is shown in Figure 108. Eight thermocouples were placed in the flame to record the fire temperature. Nine minutes fifty seconds (590 seconds) after ignition of the fuel, the bomb with the live Nose Fuze M904E2, Candidate No. 1 sleeve and Insunol paint on the adapter ring deflagrated. The reaction was minor. The thermocouple data for the Fuze M904E2 and M148 Adapter Booster are shown in Figures 109 and 110. The second reaction occurred at ten minutes twenty-five seconds (625 seconds) after the start of the fire. The bomb contained an inert Nose Fuze M904E2, Candidate No. 1 sleeve and a washer of Candidate No. 1 material cemented to the face of the adapter ring. The reaction was a detonation. The nose of the bomb was peeled back. This is shown in Figure 111. The thermocouple data for the fuze and adapter booster is shown in Figures 112 and 113.

The third bomb contained an inert Nose Fuze M904E2, Candidate No. 1 sleeve and a live M148 Adapter Booster with the adapter ring costed with Insunol intumescent paint. A deflagration occurred eleven minutes fifty seconds (710 seconds) after the start of the fire. The reaction was mild. Figure 114 is a typical thermogram




FIG. 108 EXPOSED VIEW OF THERMOCOUPLES INSTALLED IN AN ADAPTER BOOSTER




FIG. 110 FUZE TEST NO. 23-THERMOGRAM OF AN INERT M148 ADAPTER BOOSTER CONTAINING A M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE






FIG. 111 FUZE TEST NO.23 PHOTOGRAPH OF MK 82 BOMB AFTER COOK-OFF TEST







FIG. 113 FUZE TEST NO. 23 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING A FUZE M904E2 PROTECTED WITH CANDIDATE NO. 1 SLEEVE










FIG. 114 FUZE TEST NO. 23 THERMOGRAM OF AN INERT M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE

of a thermocouple in the inert Fuze M904E2. Figure 115 indicates the cook-off temperature and time of the live adapter booster. The plateau on the adapter booster thermogram may indicate when intumescence is occurring; however, it does not indicate the intumescent temperature because of heat loss along the adapter booster.

The fourth bomb contained a live Nose Fuze M904E2 with Candidate No. 1 sleeve. A washer of Candidate No. 1 material was cemented to the face of the adapter ring of the inert M148 Adapter Booster. Cook-off occurred in thirteen minutes thirty seconds (\$10 seconds). The reaction was a deflagration. The time temperature plot of the fuze is shown in Figure 116. The time temperature plot of the adapter booster is shown in Figure 117. Here we notice the plateau is gone.

The thermal protection of the paint and washer were similar and were within the experimental error of this measurement. From an operation viewpoint, the washer would be in the way in assembly of the adapter booster into the bomb and difficult to completely bond to the adapter ring. For these reasons the washer was judged to be impractical. As a result of this test, the washer was discarded in favor of the intumescent paint. In all M148 Adapter Boosters for future tests the adapter ring face was coated with the Insunol system (intumescent paint and barrier coat).


The formulation of the Insunol system and the source of material are noted on NAVAIR Dwg. No. 599AS105 included as Appendix D.

### Fuze Test No. 24

Fuze Test No. 24 was conducted to evaluate the reliability of the other two fuze coverings. Two inert Nose Fuzes M904E2 were prepared, one with Candidate No. 14 sleeve and one with Candidate No. 10 sleeve. These were installed in thermally protected bombs containing live M148 Adapter Boosters. In the other two bombs two live Fuzes M904E2 were installed, one with Candidate No. 14 and one with Candidate No. 10 sleeves. The bombs contained two inert M148 Adapter Boosters. In all cases the adapter rings were coated with Insunol; i.e., 30 mils intumescent paint and a 4 mil overcoat. The thermocouple arrangement was the same as in Fuze Test No. 23. The wind velocity was 9-4 knots throughout the entire test. Six and one-half inches of fuel were used in this test. The average burning time was computed to be twenty minutes.

Thirteen minutes thirty seconds (810 seconds) after the start of the fire the live Fuze M904E2 with Candidate No. 10 sleeve and the inert adapter booster reacted. The reaction was mild and from the fuze remnants recovered after the test the fuze appeared to deflagrate. Figure 118 shows the temperature vs time plot of the Fuze M904E2 thermocouples and Figure 119 represents the thermogram of the M148 Adapter Booster, Here again, the plateau is evident.

Fourteen minutes (840 seconds) after the fire was started the bomb containing the inert Nose Fuze M904E2 with the Candidate No. 14








FIG. 116 FUZE TEST NO. 23 THERMOGRAM OF A LIVE M904E2 FUZE PROTECTED WITH A CANDIDATE NO. 1 SLEEVE




FIG. 119 FUZE TEST NO. 24 THERMOGRAM OF AN INERT M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE




FIG. 118 FUZE TEST NO. 24 THERMOGRAM OF A LIVE M904E2 FUZE PROTECTED WITH A CANDIDATE NO. 10 SLEEVE

sleeve and the live M148 Adapter Booster initiated. The reaction was rather mild and the fuze was recovered intact. Figures 120 and 121 represent typical thermograms of the fuze and adapter booster thermocouples, respectively.

The third reaction occurred fifteen minutes twenty seconds (920 seconds) after the initiation of the fuel originating from the inert Nose Fuze M904E2 protected with the Candidate No. 10 sleeve and Live M148 Adapter Booster. The reaction was mild and the fuze was also recovered. Figures 122 and 123 indicate typical thermograms for the fuze and booster.

The fourth reaction occurred fifteen minutes thirty-five seconds (35 seconds) after the start of the fire at the bomb containing a live Muze M904E2 with Candidate No. 14 sleeve and inert M148 Adapter Booster. The reaction was mild and could not be audibly or visibly detected. The only indications were from the thermocouple records. Figures 124 and 125 indicate the fuze and booster ignition times. The fire temperature thermogram is shown in Figure 126.

These results indicate that Candidates No. 14 and No. 10 sleeves are promising as protective devices for the Fuze M904E2. The next two fuze shots were designed to choose the primary and back-up fixes.

## Fuze Test No. 25

Four thermally protected inert concrete loaded bombs were again used, as in previous tests. One bomb contained a live Nose Fuze M904E2 protected with Candidate No. 1 sleeve. The M148 Adapter Booster was inert. The remaining three bombs contained inert Nose Fuzes M904E2 with Candidate No. 1, No. 14 and No. 10 sleeves assembled in Live M148 Adapter Boosters. All the sleeves were bonded to the fuze body with RTV 737.

The first reaction occurred thirteen minutes twenty seconds (800 seconds) after ignition of the fuel. The live Fuze M904E2 with the Candidate No. 1 sleeve and inert adapter booster reacted first. The reaction was rather mild, and the pieces of the adapter booster were recovered without major change. The wind velocity was 3-5 knots with occasional gusts up to eight knots. This was higher than in our previous experiments. As a result, the excursion of flame temperatures were larger than in our previous tests, and cook-off times were longer. Figure 127 indicates the variation of fire temperature with time. Figures 128 and 129 indicate the cook-off temperatures of the fuze and adapter booster.

The second reaction occurred fifteen minutes ten seconds (910 seconds) after the fuel ignition started and it was the bomb containing the inert Fuze M904E2 with the Candidate No. 1 sleeve and live M148 Adapter Booster. The reaction was mild and both fuze and adapter booster were recovered. The back of the adapter booster




FIG. 121 FUZE TEST NO. 24 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING : 1904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE




FIG. 120 FUZE TEST NO. 24 THERMOGRAM OF INERT M904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE




FIG. 123 FUZE TEST NO. 24 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE





FIG. 122 FUZE TEST NO. 24 THERMOGRAM OF AN INERT M904E2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE





1.400

1.200

TIME (1000 SEC.) 1-000

FUZE TEST NO. 24 THERMOGRAM OF AN INERT

M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE

FIG. 124

a 4H31

1200,000

VIDRE CHRINEL 5-2300




FIG. 126 FUZE TEST NO. 24 FIRE TEMPERATURE THERMOGRAM

HANNING WHITE WATER




FIG. 129 FUZE TEST NO. 25 THERMOGRAM OF AN INERT M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE




FIG. 128 FUZE TEST NO. 25 THERMOGRAM OF A LIVE M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE

cup had a large hole, due to explosive burning. The time temperature plots for the fuze and adapter booster are shown in Figures 130 and 131.

The third reaction occurred at fifteen minutes forty seconds (940 seconds). This bomb contained a Fuze M904E2 with Candidate No. 14 sleeve assembled in a live M148 Adapter Booster. The reaction was a dell'agration. The fuze was not recovered, however, the aluminum sleeve was still intact in the bomb. Figures 132 and 133 indicate the temperature of the fuze and adapter booster before and after ignition.

The fourth reaction involved the inert Fuze M904E2 with Candidate No. 10 sleeve assembled into a live M148 Adapter Booster. The reaction occurred seventeen minutes forty-five seconds (1065 seconds) after ignition of the fuel. The deflagration reaction was similar to those occurring in the assemblies. The temperature time thermogram for the fuze is shown in Figure 134. The temperature time curve for the adapter booster is shown in Figure 135.

These results indicate that the cook-off time of the fuze and the adapter booster can almost be doubled by means of a protective sleeving on the fuze and an intumescent paint system on the adapter booster.

At this time we were informed that Dow Corning no longer planned to market the RTV 737 because of production difficulties and RTV 3145 was proposed as a replacement. RTV 3145 evolves methyl alcohol on cure while RTV 737 releases acetic acid and this was considered desirable from a corrosion point of view.

Candidate No. 10 appeared to be attractive from a fire performance standpoint, however, the cost per sleeve was unattractive. Since the material is defined by a military specification alternate sources were contacted and new methods of manufacture resulted in a more favorable projected unit price. While these processing studies were in progress we were interested in determining whether the performance of the other two fixes (Candidate No. 1 and Candidate No. 14) would be affected by a change in the adhesive.

#### Fuze Test No. 26

Fuze Test No. 26 was designed to answer this question. Four thermally protected concrete loaded bombs were utilized. Two of the bombs were equipped with live Nose Fuzes M904E2 and inert M148 Adapter Boosters and two were equipped with inert Nose Fuzes M904E2 and live M148 Adapter Boosters. The Candidate No. 1 sleeves were bonded to the live fuze and the inert fuze by means of RTV 3145. The Candidate No. 14 protective sleeve were also bonded to the remaining two fuzes by means of RTV 3145. The fuzes and adapter boosters were instrumented identically as in the previous tests.




FIG. 131 FUZE TEST NO. 25 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE






FIG. 130 FUZE TEST NO. 25 THERMOGRAM OF AN INERT M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE







FUZE TEST NO. 25 THERMOGRAM OF AN INERT M904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE

FIG. 132









The first reaction occurred six minutes (360 seconds) after the start of the fire. The bomb containing a live Nose Fuze M904E2 with the Candidate No. 1 sleeve (bonded on with RTV 3145) and an inert adapter booster deflagrated. The fuze was not recovered. However, the adapter booster and bomb showed no sign of a detonation. Typical time temperature thermograms of the fuze and adapter booster are shown in Figures 136 and 137. The first peak in Figure 136 should be disregarded because of an imperfection in the magnetic tape.

The second reaction occurred twelve minutes ten seconds (730 seconds) after the start of the fire. This configuration consisted of a Candidate No. 1 sleeve bonded on an inert fuze with RTV 3145. A live adapter booster with a fixed adapter ring was used. Time temperature thermograms of the fuze and adapter thermocouples are shown in Figures 138 and 139.

The third reaction occurred with the Fuze M904E2 protected with Candidate No. 14 sleeve assembled in an inert M148 Adapter Booster deflagrated in twelve minutes forty-five seconds (765 seconds). The time temperature plots of the fuze and adapter booster thermocouples are shown in Figures 140 and 141.


The fourth reaction occurred in fifteen minutes fifteen seconds (915 seconds). The bomb contained an inert Nose Fuze M904E2 with Candidate No. 14 sleeve and a live M148 Adapter Booster. The reaction was a deflagration and was exceedingly mild. The nose fuze was recovered intact. Typical thermograms of the fuze and adapter booster are shown in Figures 142 and 143. The first peak in Figure 142 should be disregarded because of an imperfection in the tape. The fire temperature thermogram is shown in Figure 144.


These results are summarized in Table 21. It can be seen that the cook-off time of the Fuze M904E2, protected with a Candidate No. 1 sleeve, is markedly dependent upon the adhesive which is used to attach the device to the fuze. The Candidate No. 14 sleeve appears to be only slightly affected by the change in adhesive. The adapter booster with the Insunol on the adapter ring seems to be unaffected by the adhesive which is used on the nose fuze. As a result of this test the Candidate No. 1 material was eliminated from the program since insufficient time or funding was available for further testing of various adhesives. The Candidate No. 10 sleeve produced by another source per specification WS-8939 was continued since as stated previously the projected cost by a new manufacturing method was attractive.

In order to check the material a small scale fire test was performed on a sheet of the Candidate No. 10 material obtained from the new source. No difference in thermal protection could be detected from material obtained from either source. Sleeves were then fabricated by the new source for assembly on Fuzes M904E2.

MI48 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE

M904E2 FUZE PROTECTED WITH CANDIDATE NO. 1 SLEEVE BONDED ON WITH RTV 3145











FIG. 140 FUZE TEST NO. 26 THERMOGRAM OF A LIVE M904E2 FUZE PROTECTED WITH CANDIDATE NO. 14 SLEEVE BONDED WITH RTV 3145










FIG. 144 FUZE TEST NO. 26 FIRE TEMPERATURE THERMOCOUPLE

## Table 21

Cook-Off Results on Thermally Protected Concrete Loaded MK82 Bombs Containing Live and Inert Nose Fuzes M904E2 with Various Protective Coverings Assembled in Live and Inert M148 Adapter Boosters

Fuze Test No.	Nose Fuze Configuration	Adapter Booster Configuration	Reaction Time Sec.	Type of Reaction
23	Live M9C E2 with Candidate No. 1 and RTV 737	Inert T45E7 with Insunol on adapter ring	590	Deflagration
23	Inert M904E2 with Candidate No. 1 and RTV 737	Live T45E7 with Candidate No. 1 on adapter ring	625	Detenation
23	Inert M904E2 with Candidate No. 1 and RTV 737	Live T45E7 with Insunol on adapter ring	710	Deflagration
23	Live M904E2 with Candidate No. 1 sleeve and RTV 737	Inert T45E7 with disc of Candidate No. 1 material on adapter ring	610	Deflagration
24	Live M90ME2 with Candidate No. 10 and RTV 737	Inert T45E7 with Insunol on adapter ring	810	Deflagration
24	Inert M904E2 with Candidate No. 14 and RTV 737	Live T45E7 with Insunol on adapter ring	840	Deflagration
24	Inert M904E2 with Candidate No. 10 and RTV 737	Live T45E7 with Insumol on adapter ring	920	Deflagration
24	Live M904E2 with Candidate No.14 and RTV 737	Inert T45E7 with Insunol on Adapter ring	935	Deflagration
25	Live M904E2 with Candidate No. 1 and RTV 737	Inert T45E7 with Insunol on adapter ring	800	Deflagration
25	Inert M904E2 with Candidate No. 1 and RTV 737	Live T45E7 with Insunol on adapter ring	910	Deflagration
25	Inert M904B2 with Candidate No. 14 and RTV 737	Live T45E7 with Insunol on adapter ring	940	Deflagration

## Table 21 (Con't.)

Fuze Test No.	Nose Fuze Configuration	Adapter Booster Configuration	Reaction Time Sec.	Type of Reaction
<b>2</b> 5	Inert M904E2 with Candidate No. 10 and RTV 737	Live T45E7 with Insunol on adapter ring	1065	Deflagration
26	Live M904E2 with Candidate No. 1 and RTV 3145	Inert T45E7 with Insunol on adapter ring	360	Deflagration
26	Inert M904E2 with Candidate No. 1 and RTV 3145	Live T45E7 with Insunol on adapter ring	730	Deflagration
26	Live M904B2 with Candidate No. 14 and RTV 3145	Inert T45E7 with Insunol on adapter ring	765	Deflagration
26	Inert M904E2 with Candidate No. 14 and RTV 3145	Live T45E7 with Insunol on adapter ring	915	Deflagration

#### Fuze Test No. 27

The next series of tests were combined tests. The first test contained a Candidate No. 10 sleeve on a Nose Puze M904E2 with a fixed inert M148 Adapter Booster and an Inert Puze M904E2 with a Candidate No. 10 sleeve in a live fixed M148 Adapter Booster. The other two thermally protected bombs contained live Candidate No. 14 M904E2 fixed Nose Puzes with live fixed M148 Adapter Boosters. All of the adapter boosters were equipped with a steel disc .027" thick coated on both sides with .034" of Insunol including overcoat. The aluminum sleeve was coated on the top surface and inside surface with .034" of Insunol including overcoat. The front of the adapter ring also was coated with .034" of Insunol including overcoat. The adapter boosters contained thermocouples in the same position as in our previous tests. No thermocouples were placed on the fuze.

The first reaction occurred in seven minutes fifty-five seconds (475 seconds) after ignition of the fuel. The Fuze M904E2 with Candidate No. 14 assembled in a live M148 Adapter Booster deflagrated. The adapter booster cup had a large hole burned in the rear, however, the Mk 82 Bomb was still intact and there was no damage to the bomb. From the thermocouple data it appears as though the fuze deflagrated since no self-heating appeared to have taken place in the adapter booster. A typical fire temperature thermogram is shown in Figure 145. The thermogram for the Adapter Booster is shown in Figure 146.

The second reaction occurred at the bomb containing the fixed inert Puze M904E2 with Candidate No. 10 sleeve with the fixed live M148 Adapter Booster. The reaction occurred fifteen minutes twenty seconds (920 seconds) after ignition of the fire. The reaction was a deflagration. One can see from the thermogram in Figure 147 the evidence of self-heating of the tetryl in the adapter booster shortly before ignition.

The Fuze M904E2 with Candidate No. 14 sleeve in a live M148 Adapter Booster reacted next at fifteen minutes fifty seconds (950 seconds) after ignition of the fuel. The reaction was a deflagration and appears to have originated in the fuze. A typical thermogram is shown in Figure 148. The rapid rise before ignition is missing in these thermograms.

The live Mose Fuze M904E2 with Candidate No. 10 sleeve in an inert sand filled M148 Adapter Booster reacted next after seventeen minutes (1020 seconds). The reaction was mild and was considered a deflagration. A typical thermogram of the inert booster adapter is shown in Figure 149.

Because of the short reaction time taking place with the fuze containing the Candidate No. 14 sleeve and fixed live adapter booster, it was decided to repeat this test utilizin `nly live adapter boosters and live fuzes. The live adapter 'sters and live

164 UNCLASSIFIED




FIG. 147 FUZE TEST NO. 27 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH A CANDIDATE NO. 10 SLEEVE FROM A NEW SOURCE





FIG. 146 FUZE TEST NO. 27 THERMOGRAM OF LIVE M148
ADAPTER BOOSTER CONTAINING FUZE M904E2
PROTECTED WITH CANDIDATE NO. 10 SLEEVE
MANUFACTURED BY A NEW SOURCE








FIG. 148 FUZE TEST NO. 27 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING FUZE M904E2 PROTECTED WITH CANDIDATE NO. 10 SLEEVE FROM A NEW SOURCE

nose fuzes were tested together in order to determine the compatibility of the open adapter fixes with the live fuze fixes. Two tests were planned in this study due to fund limitations and scheduling limitations.

## Fuze Test No. 28

Concrete loaded bombs were coated with Insunol intumescent paint on the exterior surface. All adapter rings were also painted with Insunol (.034" thick including overcoat). All live M148 Adapter Boosters were equipped as before with a .027" thick steel disc coated on both sides with .030" thick intumescent paint plus .004" overcoat. The aluminum sleeve was coated on the top and inside surfaces with Insunol .034" thick. All protective sleeves were cemented to the fuzes (using RTV 3145), allowing forty-eight hours drying time before testing. Thermocouples were installed in the usual fashion, in contact with the explosive and in the rear booster cavity.

Seven minutes fifty seconds (475 seconds) after the beginning of the fire the Fuze M904E2 protected with Candidate No. 14 sleeve deflagrated. The reaction was mild. A photograph of the pit after the test is shown in Figure 150. The reaction appears to have originated in the fuze, judging from the appearance of the adapter booster curve shown in Figure 151. The average fire temperatures was 1650°F and is comparable with the other fuze test.

The second reaction (deflagration) occurred eight minutes (480 seconds) after the ignition of the fuel. The Fuze M904E2 was protected with a Candidate No. 10 sleeve. Again the reaction appears to have originated in the fuze section from the appearance of the thermocouple thermogram shown in Figure 152.

The third reaction occurred nine minutes (540 seconds) after ignition of the fuel. The reaction took place at the bomb equipped with the Candidate No. 14 sleeve. The bomb jetted like a rocket for approximately thirty seconds. The fuze body was recovered with the protective sleeving still cemented to the fuze body. A close-up of the ablated sleeve is shown in Figure 153. The reaction is believed to have originated in the fuze. The adapter booster thermocouple trace is shown in Figure 154.

The fourth reaction occurred on the assembly vith Candidate No. 10 sleeve on Fuze M904E2 fourteen minutes thirty seconds (870 seconds) after the ignition of the fuel. The reaction was a deflagration. The fuze was recovered outside of the pit and is shown in Figure 155. The adapter booster is believed to have caused this reaction. Its thermogram is shown in Figure 156. The rapid temperature rise before ignition is indicative of a booster adapter reaction.

The short reaction times of the three of the four assemblies in Fuze Test No. 28 caused a great deal of concern. Three

167 UNCLASSIFIED






FIG. 150 PHOTOGRAPH OF PIT AFTER COOK-OFF TEST







TO DE TEST TO THE PART OF A SERVICE A SERVICE A HERALE MOUNT SERVE AFTER TEST




FIG. 154 FUZE TEST NO. 28 THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE FROM A NEW SOURCE






FIG. 156 FUZE TEST NO. 28 THERMOGRAM OF A LIVE M148 ADAPT'S BOOSTER CONTAINING M904E2 FUZE PROTECTED WITH CANDIDATE NO. 10 SLEEVE

possibilities were postulated. The first possibility considered was that the potective sleeving contained occluded air which when heated caused the sleeves to fracture and fall off. This was rejected since the Candidate No. 14 fuze covering was still intact on the fuze body, yet reaction time was only 540 seconds. The second possibility considered was that the heat transfer through the three unprotected holes inserted in the fuse covering for the stop screw, upper observation window and setting index locking pin caused early reactions. Maximum heat transfer through these areas occurs when the openings are directed toward the fire. On a close review of the photograph taken before the test, the fuzes with the shorter cook-off time were orientated in this unfavorable position. These photographs are shown in Figures 157 and 158. It was confirmed that in the case of three assemblies the holes are oriented toward the rising fire. The third possibility was that the Insunol was not effective as an insulator in the closed adapter booster situation since it must intumesce before it performs an insulation function.

## Puze Test No. 29

The last experiment in this fuze series was designed to determine (1) whether orientation of the fuze influenced reaction times, and (2) whether the Candidate No. 10 material used as a disc and washer in the M148 Adapter Booster would be an improvement over Insunol.

Four thermally protected concrete loaded bombs were used as before. The same thermocouple arrangement was used as in the previous tests. All fuzes and adapter boosters were explosive loaded. The sleeves were bonded to the Nose Fuze M904E2 with RTV 3145. Instead of the intumescent paint, a disc and washer of Candidate No. 10 material .100" inches thick were used. These are shown in Figure 159. The aluminum sleeve was reduced in length to accommodate the added thickness of the disc and washer. The length was cut from a nominal length of 3.290 to a length of 2.906". All of the adapter ring faces of the adapter booster were coated with Insunol.


Two Fuzes M904E2 were protected with Candidate No. 10 sleeves. One fuze was oriented with the openings (holes and slots) twward the fire and the other away from the fire. The other two Fuzes M904E2 were protected with the Candidate No. 10 sleeves. One fuze was oriented with the openings toward the fire, the other oriented away from the fire. The wand velocity was higher than usual and was between 3-5 knots. The fire temperature was lower than in our previous tests, averaging approximately 1480°F (Figure 160).

The first reaction was experienced thirteen minutes forty seconds (820 seconds) after the start of the fire. The Fuze M904E2 protected with Candidate No. 14 sleeve with the openings oriented toward the fire detonated violently, destroying half the bomb. The

174



THE WINDS AT LATE OF BUILDING WESTATES INDICATED



FIGURES FOR TEST CONTROL AND TO CHARACTER TALL TO ASTERNED AND THE NEW THEOLOGICAL TOWARD FIRE



PLUST RESTRICTED TO SECRET FRANCE DITC AND TAKEN A HER AND A SECRET OF A MATERIAL.




FIG. 160 FIRE TEST NO. 2º THERMOGRAM OF FIRE TEMPERATURE THERMOCOUPLE

FIG. 161 FUZE TEST NO. 2" THERMOGRAM OF A LIVE M148 ADAPTER BOOSTER CONTAINING FUZE M904E2 PROTECTED WITH CANDIDATE

reaction seemed to occur in the fuze, after examining the adapter booster thermcouple data. The time temperature plot of the thermocouple is shown in Figure 161.

The second reaction occurred in fourteen minutes fifty-five seconds (895) seconds) with the fuze protected with the candidate No. 10 sleeve. Again, the holes were orientated toward the fire, and again the bomb detonated. This resulted in banana peeling of the front of the bomb and is shown in Figure 162. The thermocouple plot is shown in Figure 193. The reaction again appears to have started in the fuze.

The third reaction occurred sixteen minutes (960 seconds) after the start of the fire. The Fuze M904E2 contained the candidate No. 10 sleeve with the holes orientated away from the fire. The reaction again resulted in a detonation, destroying the front end of the bomb. The reaction appears to have originated in the fuze. The adapter booster thermocouple trace is shown in Figure 154.

The last fuze containing the candidate No. 14 sleeve reacted in nineteen minutes forty seconds (1180 seconds). The adapter booster appeared to have started to self-heat, however, the fuze is believed to have caused the reaction due to the low exotherm produced. This is shown in Figure 105. The bomb detonated just as the fire was dying out. The fuze cover was oriented with the opening away from the fire.

These results of Puze Tests 27, 28 and 29 are summarized in Table 22,

It appears that (1) the orientation of the holes and slots in the sleeve downward contribute to the rapidity of cook-off and (2) intumescent paint does not perform its insulation function in the closed adapter booster application.


## SUMMARY AND CONCLUSIONS

The Mk 80 series of bombs are composed of three major elements that are vulnerable to cook-off namely (1) fuzes (2) adapter boosters and (3) the main charge. The work on extending the cook-off of the main charge has been carried out under another program. It was a desired goal that the fuze and booster cook-off time exceed the main charge.

(1) Cook-off tests on an unprotected Nose Fuze M904E2 in a thermally protected H-5 loaded Mk 82 Bomb (coated internally with 1/4" high temperature hot melt and externally with intumescent paint) cooked off in approximately five minutes. The Mk 346 Fuze cooked off in approximately eight minutes. A solution to the Mk 346 Fuze cook-off problem was not pursued. Fire tests indicated that when the flame was directed into an M149 open adapter hooster cavity, assembled in a bomb, (assisted by at least a 10 knot wind) cook-off occurred in less than four minutes. Under calm conditions, time of 16 minutes or more were experienced.

179 UNCLASSI FIED





The THE THEROCEAU OF A HIG ADAPTE RECOTER - FULL SHO, 1887 TOOL TOTAL TO THE WOOD AND THE GOARD AND THE TOTAL OF THE CONTRACT OF THE WOOD AND THE TOTAL OF THE WOOD AND THE PROTECTED THE ANDIDARE MO, 15 THERE

SHIP ATHEANNING NO. 14 SHINE

The second second




FIG. 160 1 JEE TEST 100, 2- THINKY CHAN OF A LIVE WIND ADAPTER BOOSTER CONTAINING FOR MANAGE PROTECTES, WITH CANDIDATE WO. TO LETCH

Table 22

Cook-Off Results of Nose Puze M904E2 and Live M148
(T45E7) Adapter Booster - Combined Test Results

Puze Test No.	Nose Fuze M904E2 Configuration	Adapter Booster Configuration	Reaction Time Sec.	Type of Reaction
27	Candidate No. 10 Sleeve and RTV 3145. Live Puze.	Inert T45E7 and 34 mils Insunol on adapter ring, disc and aluminum sleeve.	1020	Deflagration
27	Candidate No. 10 Sleeve and RTV 3145. Inert Puze.	Live T45E7 and 34 mils Insunol on adapter ring, disc and aluminum sleeve.	920	Deflagration
27	Candidate No. 14 Sleeve and RTV 3145. Live Puze,	Same as above	475	Deflagration
27	Same as above	Same as above	950	Deflagration
28	Candidate No. 10 Sleeve and RTV 3145. Live Fuze.	Same as above	480	Deflagration
28	Same as above	Same as above	870	Deflagration
28	Candidate No. 14 Sleeve and RTV 3145. Live Puze.	Same as above	475	Deflagration
28	Same as above	Same as above	540	Deflagration
29	Candidate No. 10 Sleeve and RTV 3145. Live Puze. Slot directed toward fire.	Eixe T45E7 and 34 mils Insunol on adapter ring. Disc and washer of Candidate No. 10.	895*	Detonation
29	Same as above. Slot away from fire.	Same as above	1160*	Defantion
<b>2</b> 9	Candidate No. 14 Sleave and RTV 3145. Live Fuze. Slot directed toward fire.	Same as above	8 <b>20</b> •	Detonation
59	Same as above. Slot away from fire.	Same as above	960*	Detonation

<sup>\*</sup> Fire temperatures lower than in the other tests. The average fire fire temperature was 1480. .

183 UNCLASSIFIED

- (3) Exploratory tests on possible approaches to extend fore cookoff indicated that a sleeve of candidate No. 1 material, cemented to
  the exposed cylindrical portion of the Fuze M904E2, extended the cookoff time and this approach was pursued in developing a cook-off fix.
  A screening program was carried out involving some 15 candidates
  possessing hysical properties ranging from thermoplastic material
  to rubber the materials. Some were eliminated based on poor thermal
  performance, others were eliminated because of poor performance under
  environmental treatment of temperature and humidity.
- (3) A series of fire tests in the field reduced the fuze coverings to three, namely, candidates No. 1, No. 10 and No. 14. Candidate No. 1 (an elastic material) requires a high temperature adhesive for bonding to the fuze and it was dropped when the adhesive initially used was no longer available commercially, and no adequate replacement could be readily found.
- (4) Candidate No. 14 required the greater thickness afforded by a truncated cone to provide acceptable cook-off time. The material was inexpensive enough to allow this increase in thickness. Under conditions of exposure to extreme temperature (-66°F to +150°F) severe pracking occurred and the greater dismeter configuration reduced the number of types that could be placed in each package from 12 to 0.
- (E) Sandidate No. 10 a filled butadiene-acrylonitrile polymer (military specification material) when fabricated into a sleeve 1/4" in thickness, and bonded to the Fuze M904E2 with RTV 3145, fulfilled every requirement. It produced outstanding char, had good environmental performance, and twelve fizes could be packaged with this sleeve on the fuze.
- (6) Candidate No. 14 and No. 10 sleeves were selected for final evaluation.
- (7) A heat insulator on the face of the Adapter Ring of the Adapter Booster to interrupt the heat path was found necessary as a part of the Puze MCO4E2 fix when the 1/4" thickness sleeve was used. Washers of camidate material No's 1 and 10 were tested and found satisfactory from a thermal protection point of view, however, they appeared impractical from a ship board handling standpoint. Intumescent paint gave comparable protection and was chosen as a fix as more acceptable on board ship than materials that would interfere with M148 Adapter Fooster installation into hombs. An internal disc and washer of candidate No. 10 material was also included in the adapter booster. This corribation was procured for evaluation.
- (0) Cook-off times in excess of 12 minutes were obtained with the complete fix (M904E2 Paze with candidate No. 16 sleeve, M149 Adapter Booster with intrmescent paint on scapter ring and candidate No. 10 washer and disc internally), however, detenations were the final action. It was suspected that the candidate No. 10 material out-gazed considerably at elevated temperature and together with

# UNCLASSIFIED NOITE 71-124

intumescense probably provided favorable conditions for confinement of the explosive and consequent violent reaction. A rigid phenolic material for the disc and washer would have been a better choice.

- (9) Orientation of the fuze so that the holes and slots in the sleeve were directed downward caused shorter cook-off times than when the openings were up.
- (10) Cost and time precluded a program of extensive testing and the establishment of statistical confidence in a minimum fuze cook-off time attained by the fixes, however, the limited results tests indicate that at least a 10 minute thermal protection was obtained for both the M904E2 Fuze M148 Adapter Booster combination or the adapter booster without a fuze.

#### ACKNOWLEDGEMENT

The author wishes to thank Mr. David Dancer for his invaluable assistance in the data reduction and in the theoretical analysis of the data, and Mr. H. Cleaver for the design and fabrication of the pin switch circuit.

#### REFERENCES

- 1. Gordon, W., and McMillan, R. D., "A Study of the Temperature Distribution within Aircraft-Fuel Fires", NAVWEPS 8277, August 1963.
- 2. Takata, A. N., et al, "Final Report of Fire and Impact Tests, Joint AEC-DOD Vulnerability Program", AFSWC TDR-62-132, DASA 1276, 1963 (SRD).
- 3. Bader, B. E., "Heat Transfer in Liquid Hydrocarbon Fuel Fires", SC DR 320-63, Sandia Corporation, February 1964.
- 4. NOL 1tr 043:BL:sw 8010 Serial No. 4683 of 17 August 1971 to NMC, Paint Mugu, California and NAVAIRSYSCOM.

185 UNCLASSIFIED

# UNCLASSIFIED NOIFR 71-124

#### APPENDIX A

U. S. NAVAL ORDNANCE LABORATORY White Oak, Silver Spring, Maryland

233:HC:jej

1 July 1969

From: Harry Cleaver To: NOL Files

Subj: Pin Switch Control Box

Abst: Pin Switch circuits are being used in the Bomb Cook-off program to establish the origin of any detonation wave in the event that detonation does occur. Operating instructions and a circuit description for the pin switch control box are contained in this note.

Encl: (1) Display of Probes Triggered in Order - Figure 1 and Pin Switch Circuit - Figure 2

(2) Pin Switch Circuits - Figure 3

(3) Pin Switch Control Box Schematic - Figure 4

## OPERATING INSTRUCTIONS

- 1. Attach the multiconductor pin switch input cable to the side of the control box. A grounding switch is provided to short the input cable while personnel are setting up the test model at the burning pit site. This switch can be left on the grounded position at all times other than when the control box is to be operated. To put the box into operation, turn on the power switch and unground the input cable. The red READY light will then go on. Adjust the capacitor voltage to the level desired using controls in lower left hand section of top panel.
- 2. Test each pin switch circuit for external shorts. Test one circuit at a time using the 12 position (10 probes and 2 off) selector switch and the pushbutton TEST switch.
  - A. Set up the oscilloscope controls for
    - + INTERNAL DC TRIGGERING
    - 5 VOLTS/CM vertical sensitivity\*
    - 50 MICROSECONDS/CM sweep time\*
- B. Use either a differential preamplifier operated in the A-B DC mode or a dual trace preamplifier operated channel A normal, channel B inverted, in the ADDED ATGEBRAICALLY mode.
- \* or as dictated by voltage level and probe placement.

A-1 UNCLASSIFIED

#### Subj: Fin Switch Control Box

- C. Connect points marked CHAN A and CHAN B to the A and B inputs to the oscilloscope.
- D. Set selector switch to probe I position and, adjusting the oscilloscope trigger level and stability, test for a signal from pin switch number one. Refer to Figure I for the signal to be expected from any given probe.
- E. Test odd numbered pin switch probes 1, 3, 5, 7, 9 adjusting oscilloscope triggering as needed.
- F. Change the oscilloscope internal triggering from POSITIVE to NEGATIVE to test for the even numbered probes.
- Q. Adjust the trigger level and stability for negative triggering and check probes 2, 4, 6, 8, 10.
- H. Absence of a test signal for any probe circuit indicates a shorted probe. Since a test signal can be generated whether the pin switch probes are connected or not, breaks in the input cable cannot be detected. There is no easy way to check for open circuit continuity.
- I. Since I know nothing about the tape recorder to be used with this control box, no mention will be made of its checkout or operation. Ten separate output connectors are provided for use with the tape recorder. All the signals going to the tape recorder are negative in polarity and of the same amplitude which is equal to the signal from probe No. 1.
- 3. When all the probes have been checked out and the system is ready, the final oscilloscope control settings are to be as in 2A above. The triggering level and stability should be set so that a test signal of the lowest positive amplitude (signal from probe No. 5) will trigger the sweep. This means that the oscilloscope will trigger upon the first pulse generated by any odd numbered probe.

#### THEORY

1. Figure 2 shows the basic pin switch circuit. The capacitor C is charged through a relatively high resistance  $R_1$  and  $R_2$  to the potential of the supply voltage. Since  $R_2 << R_1$ ,  $R_2$  can be neglected in discussing the capacitor charging operation. When the pin switch is closed, the capacitor discharges through  $R_2$  generating a single pulse. The charging time constant  $R_1$ C is made much larger than the discharge time constant  $R_2$ C to avoid any regeneration of the signal during the experimental time interval.

The line resistance R<sub>i</sub> represents the total resistance in the connecting wires leading to the pin switch. In most cases this

Subj: Pin Switch Control Box

resistance is negligible but in the present situation it is not. There is at least 1000 feet of No. 22 AWG copper wire leading to the test site with an additional length of about 60 feet of type K thermocouple wire added on the end. Taking a value of 16 ohms per 1000 feet for the copper wire and 2.4 ohms per combined foot for the thermocouple wire we have a line resistance of nearly 180 ohms. This resistance must be used in computing the RC discharge time constant. Being in series with the discharge path resistor R<sub>s</sub>, the line resistance acts to reduce the signal amplitude seen by the recording instruments by virtue of its voltage drop.

In practice a number of identic. pin switch circuits are used in a given experiment. The pin switches are physically displaced at a known separation in the test object. Closing of the pin switches by the event under study generates a pulse pattern which is studied for time displacement between signals.

2. Figure 3 is a partial schematic of the circuits used to produce the display shown in Figure 1. The purpose of such a display is to provide each individual probe with its own identifiable signal characteristics. The pulses as shown vary in amplitude, polarity, and width. There are 10 circuits divided into groups of 5 each. The odd numbered circuits go to oscilloscope channel B while the even numbered circuits go to channel A. All pulses generated by the circuits have negative polarity. Signals to the oscilloscope B channel are inverted by the A - B operation and appear as positive in the display. Signals to channel A are not inverted and appear negative in the display. Amplitude variation is achieved by holding the total discharge path resistance constant at 51 ohms but picking off the output signal through various resistor divider networks at approximately full signal, 2/3, and 1/3 full signal. Pulse width variation is achieved by using different capacitor values to change the RC discharge time constant.

The charging time constant for the first six probe circuits is 2.2M ohms x .05 mfd or 110 milliseconds. Discharge time constant, assuming 180 ohms for  $R_{\rm L}$ , is 230 ohms x .05 mfd or 11.5 microseconds. The remaining four circuits have a .1 mfd capacitor which doubles their time constant to 220 milliseconds for charging and 23 microseconds for discharging.

The diodes shown in Figure 3 are used to isolate the circuits from each other. The resistor connected to the signal output terminal is used to provide a comparable time constant on the anode side of the diode string. The tape recorder connections are made at the capacitor-resistor junction so that the full signal voltage is sent to the tape recorder. Each signal to the tape recorder is recorded on a separate track so unique characteristics are not nesded for identification.

Subj: Pin Switch Control Box

3. Figure 4 is the complete schematic for the control box showing all ten pin switch circuits. Two parts not discussed so far are the power supply and the test circuit sections.

The power supply transformer applies stepped down full wave rectified voltage to a resistor-capacitor filter. An output voltage of 36 volts DC is developed across the 100K ohm adjustment pot. Power, ripple, and regulation requirements are minimum for this application and aided the simple design.

A silicon controlled rectifier (SCR) is used in the test section to simulate the pin switch. The SCR is connected to any desired pin switch circuit using the 12 position selector switch such that the SCR is in parallel with the pin switch probe. A 150 ohm resistor is used in series with the SCR to represent the line resistance. The test signal generated will then appear similar to the true signal. The SCR is triggered by a pulse from the 0.1 mfd capacitor discharging through the 51 ohm gate lead resistor when the test button is actuated. The 100K and 13K ohm divider holds the voltage on the capacitor to just over 4 volts. This type of capacitor discharge triggering was used because of the low current output capabilities of the power supply section.

HARRY E. CLEAVER Chemical Engineering Division

Literary of the same




FIG ! DISPLAY OF PROBES TRIGGERED IN OFLER




FIG2. PIN SWITCH CIRCUIT





FIG 3. PIN SWITCH CIRCUITS

Enclosure (2)



#### APPENDIX B

```
POCOTAC. 1900.CM100000.52300593.126.012002.
ATTACH(ARC . NOLRIA)
COPYNIO DEF . ABC
RETURNIARCE
FINIL
LOADILGO
REQUEST. TAPES. HI.S. (LEVINES/NOSTIC)
REQUEST. TAPERR. LO. (CALCOMP/PING)
DEF.
PENINDIABOL
CALCHY, 13, ABC
SMOOTH . 2 . APC
      PRODUKAN STACINAPUTA BUTALIATARES TO CIACIONA "F"
                   TAPET. TAPES . TAPESS)
     1 TADER.
      OIMENSION ITICH(501.1504(501.X. 31/(50).10 57/(50).17 4P=(5/).
     2 TECATA(2001-TIDATA(2001-U ATA(801-X)341/129(-501-1116-(50)
                                                       15460 1 (51)
     3 . (LICH(50).SMTEMP(200).
      DATA A.M.C/ -.6598..02/07.5.29 11-1/
      TATA D.F/ 1.96.2.72/
      DATA ICTEL TOTES THE THEY
    4 FORMAT (ALL
      oras (5.5) Mpons
      ERITE (6.5) MPROP
      00 999 L = 1.NPROB
      NDATP = 0
      J = 0
      1CY1 = 0
      1CY = 1
      IFLAG = 0
      00 103 1 = 1.50
  103 XDATA(I) = 0.
      00 203 1 = 1.50
      00 203 J = 1.200
  203 XXDATALJell . 0.
      READ (5.3) TIMING. TIMST. TEMI. TEM2
      WRITE(6.3) TIMINC.TIMST.TFM1.TEM2
    3 FORMAT (AFTO.3)
      READ(5.5) NCH. NSHOT . NSKIPF .
                                          N.NPTICH.IRE . IPLOT.
                                                                       IVIC
     2 .NSKIPD
      ANCH # NCH
      WRITE(6.5) NCH.NSHOT.NSKIPI.
                                           NoNETICA, IREW, IPLUI.
                                                                        IVID
     2 .NSKIPD
      READ(5.5) NTICH. (ITICH(1).1 =1.NTICH)
      WRITE(6.5) NTICH. (ITICH(1) . I =1.NTICH)
      READ(5.5) NSCH. (15CH(1).1 =1.NSCH)
      WRITE(6.5) NSCH. (15CH(1).1 =1.NSCH)
      READ(5.5) NETCH. (ILTCH(1). I#1.NETCH)
      WRITE(6.5) NLTCH. (ILTCH(1), I=).NLTCH)
      READ (5.555) (ISMOUT(J) .J=1.NCH)
      WRITE(6,555) (ISMOCT(J) .J=1.NCH)
```

```
SES FORMATIANTIL
    FORMA! (1615)
    ANSHOT = ASHOT
    IF (NSKIPF . FQ. O) 10 TO 996
SKID FILES
PROGRAM COMES HERE IT YOU READ IN ! MALCE OF MSKIPE . GT. )
                           OR IF PROGRAM FINDS THAT VI SE CHANNELS SE. LOT OF
PROPER ORDER OF IF THE STON OF A-TICH IN ACT + NOR -
890 CONTINUE
THE FOLLOWING PROCESURE TO SKIP A FILE WILL "A" WORK IF THE NO OF RECURS
ON THE FILE EXCEEDS 10000
    no cor J = 1.NSKIPF
    pn 004 1 = 1.10000
    BEAD IN 41 INTH
    1F | FOF (N) 1 905.994
704 FONTIN F
00% (04TINUE
    IF (!FLAG) 30.996.30
996 CONTINUE
     1CY = 0
    W# ! * F ( 6 . * )
   1 FAD" AT [ 141] ]
    CONTINIE
     READ(N.10) (10A1A(1), 1516N(1), J' T ((1), 1) XPC(1), 1 =1.10)
 10 FORMATILO(13.41.16.11.1X))
     IF (EOF(N)) 30.11
  11 CONTINUE
     1F (10CHEC(N)) 30.9011
ONIT CONTINUE
     IF (NBTICH .LT. 0) GO TO 210
     NRTJ = NRTICH - IVID
     ISIGA = TOTGNINGTU)
     IF (15163 .EQ. 15161 .OR. 15163 .EQ. 15162) 60 10 210
    WRITE(6.10) (IDATA(M).ISIGN(M).JOATA(M). (EXPO(M). M #1.10)
    WRITE(6,110)
 110 FORMATCHIGH FOR THIS CYCLE, THE SIGN OF METICH IS NEITHER + NOR +.
    2 PROGRAM IGNORES BATA FROM THIS CYCLE AND ALL SUCCEEDING CONLESSI
     NSKIPF = 1
     TFI AG = 1
     GO TO 890
 210 CONTINUE
     DO 15 [ = 1.10
     NDATP = NDATP + 1
     IF (NDATP .LE. NSKIPD) GO TO 15
     ្រ ≅ ប + 1
                           GO TO 1015
     IF (J .LE. NCH)
 START A NEW CYCLE
     1CY = 1CY + 1
     J = 1
1015 CONTINUE
     DIVI + L = DIVL
    SIF (TOATALL) - JUIN) 310,510,310
 310 WRITE(5.10) ([DATA(M).ISICA(-).JEATA(M).IE 400("). M =1.10)
     WRITE(6,410)
 410 FORMATILIAH FOR THIS CYCLE, THE CHANNELS ARE NOT IN PROPER ORDER.
    2 PROGRAM IGNORES DATA FROM THIS CYCLE AND ALL SUCCEEDING CYCLES.)
     NSKIPF # 1
```

```
1FLAG # 1
GO TO 890
  510 CONTINUE
   20 FORMATI
               /10(1X+14+FR+1)/)
      (I)ATAU = JDATA(I)
      IFXP = IFXPO(I) - 3
      XXDATA(ICY.J) = XDAT/10.**IEXP
C A CYCLE HAS BEEN COMPLETED
      IF (J .FQ. NCH) !(Y) = !(Y) + 1
  15 CONTINUE
      IFIL .NE. 2 .OR. NDATP .LF.60001 GO TO 2
  30 CONTINUE
      ICY = ICYI
      IF (ICY .LE. 0) GO TO 610
     DO 600 J = 1.NCH
      AJ1 = J - 1
      71VI + L = CIVL
     00 0 1 #1.NSCH
      IF (JVID.FO. ISCH(II) GO TO KOO
   9 CONTINUE
     CIVI + L = LA
     PN = ANSHOT + AJ/100.
     DO 590 I = 1.NTICH
      IF (JVID .FQ. ITICH(I)) GO TO 600
 590 CONTINUE
     DO 595 I =1.NSCH
      IF (JVID.FR. ISCH(I)) GO TO 600
 595 CONTINUE
     AJ= J - NRTJ
      TIMINI * AJ* TIMINC
     DO 597 M = 1.1CY
     UTIL = A - ABS(XXDATA(M_*J))
     UTIL1 = B + B - 4. * UTIL * C
      TEDATA(M)=((SQRT(UTIL1) -9) / (2. *C))/ 1000.
      IF INSTICH .LT. 01 GO TO 4987
     TIDATA(M) = (XXDATA(M.NBTJ) + TIMIN1) / 100.
     GO TO 5987
49A7 AM1 = M - 1
      TIDATA(M) =(TIMINC + (ANCH+AM1 +AJ1) + TIMST)/ 100.
5987 CONTINUE
 597 CONTINUE
6987 FORMATIZAH UNSMOOTHED DATA FOR CHANNEL . 15 . /
                                                   112H TIME( 100SEC)
    1 8X.
                                                                       TIME
    2
       TEMP(1000F)
                             TIME ( 100SEC)
                                                  TEMP(1000F)
    31 100SEC1
                      TEMP(1000F))
7987 FORMAT(6F20.4)
     WRITE(6.6997) JVID
     WRITE(6.7987) (TIDATA(M).TEDATA(M).M=1.ICY)
      IF (IPLOT .LE. 0) GO TO 610
     TEMMX = TEM]
     DO 598 1 . 1.NLTCH
     IF (UVID .NE. ILTCH(I)) GO TO 598
     TEMMX . TEM2
     GO TO 599
 508 CONTINUE
 599 CONTINUE
      IF (IPLOT .GT. 2) GO TO 602
```

```
IF (15MOST(J) .GT. 1) GO TO 602
    CALL CALCUTION, TIDATA, TEPATA, C.O., 15., C., TEMEX, 7.9, 10., 2 13HVIDAR CHANNIL, 13, 14HTIME - 1005EC, 4,17HTEMP - 1000 DEG F,
    3 17.PY.181
 AND CONTINUE
     IF (154001(J) . LF. 0) CO TO 600
     TALL SMOOTH (TEDATA, SHTEMP, 2, 5, 1CY)
                  SMOCTHE PATA FOR CHANN' 1 . 15 . /
8987 FORMATIOSH
                                                       112H TIME ( 196 - 1)
    1 8X .
                                                      TEMP(1000F)
                              TITE LIONSECT
    7 TEMPLIONNET
                      TEMP(IODOF))
    1 100SFC)
     WRITE(6.8987) JVID
     WRITE(6.7987) (TIPATA(V), CITEMP(M), MET. ICY)
     IF (IDENT - 2) 600.603.601
 AND CONTINUE
     F7) = -0*
     CALL CALCATORY TIMATA, SHTEMP . 0.0.15. . . TEMMX . 7. 0.10.
    2 13-110AR CHANNEL . 13 . 14 .TIME - 1005EC . . . THIEMP - 1000 DEC F.
     3 17 .PN . 181
 SOC CONTINUE
 ALC CONTINUE
     IF (TOPE .ST. O) PENIME A
 son CONTINUE
      CALL CALCULTO.O.1
      STOP
      END
```

NOT REPRODUCIBLE

#### APPENDIX C

PAST COOK-OFF TEST SPECIFICATION FOR MARK 80 SERIES LD BOMBS\*

## 1. Fast Cook-Off Test Arrangement

Test Pan Size - Minimum test pan size for MARK 80 series LD bombs is 24' square. Maximum pan size is 35' square.

Test Pan Construction - The test pan may be constructed on either a semi-permanent basis with steel plate, or, if it is expected to be destroyed by the ordnance being tested, it may be constructed in a cheaper manner from earth and polyethylene.

Providing a Level Surface for the Flame - Water should be used to fill the bottom of the pan to provide a level surface for the fuel.

Fuel Specifications - Fuel to be used should be JP-5 aircraft fuel when available, or JP-4 aircraft fuel as an alternate. The quantity of fuel should be sufficient to cause a reaction of the ordnance, or to insure a 15-minute fire, whichever is shorter (1500 gallons in the 24 pan will last approximately 15 minutes).

Fuel Ignition - For ignition of the aircraft fuel 20 gallons of gasoline and/or one gallon of ether should be added after the fuel is poured, when using JP-5. A suitable flame producing device should be used to initiate the fire, such as a thermite grenade, squib and powder bag, etc., and these should be in at least four locations so as to initiate burning over the entire fuel surface as rapidly as possible. Flame buildup time to 1000°F should not exceed 35 seconds.

Weather Conditions - For an unshielded 24' pan, a wind of three knots or less measured within 1000 feet of the test site at the level of the test item(s) is acceptable. For the 35' pan, a five knot wind or less measured within 1000 feet of the test site at the level of the test item(s) is acceptable.

Average Flame Temperature - An average flame temperature of 1650°F or greater at the weapon will be considered a good test. This average temperature is arrived at by averaging flame temperature from the time the flame reaches 1000°F or, in the case of live ordnance, until there is a reaction.

\*THIS SPECIFICATION IS PRELIMINARY AND IS INTENDED FOR USE BY NWL/DAHLGREN, NWC/CHINA LAKE, NOL/WHITE OAK, NAD/CRANE, AND NMC/PT MUGU ONLY.

> C-1 UNCLASSIFIED

## 2. Test Item(s) Placement

Height of Test Item(s) (Live and/or Inert) Above Fuel - The lowest item(s) should be suspended with the centerline between 36" and 66" above the fuel surface.

Attitude - The test item(s) should be suspended with the centerline parallel to the fuel surface.

Suspension of the Test Item(s) - The test item(s) should be suspended above the center of the pan by the lugs used to hang it on the aircraft.

Test Item(s) Configuration - The following configurations are to be used:

- a. All-up round; i.e., including operational fuzes and fin assembly.
  - b. Inert fuzes and no fin assembly.
  - c. Additional operational configurations as required.

#### 3. Instrumentation

Thermocouples - Iron-constantan or chromel-alumel thermocouples shall be used to instrument the test item(s) internally and chromel-alumel thermocouples shall be employed externally.

Thermocouple Locations - External thermocouples shall be located in a horizontal plane coincident with the centerline of the test item(s). A minumum of four thermocouples should be used, spaced equally around the test item(s), one at each end and one at each side, one to six inches from the test item(s).

Suggested Thermocouple Records - Sampling and/or continuous temperature recorders will be used. When using sampling recorders no more than four seconds shall elapse between cycles; that is, from TC 1 through all TC's back to TC 1.

Camera Coverage - Color motion picture cameras will cover each test from at least two directions 90° apart. Both normal (24 fps) and high frame rate (48 - 200 fps) cameras may be used to provide complete coverage. Still cameras and/or motion picture cameras will be used for documentary purposes.


Time Records - Complete time-to-event histories of each test will be kept. This record may be obtained from thermocouple records in some cases, depending on the methods of recording. Ignition of the fuel will serve as Zero time in all cases. The time when the fire temperature first exceeds 1000°F (as measured by one or more of the external thermocouples) is used as the point at which the test item

C-2 UNCLASSIFIED

is considered engulfed in flame. This time will be 35 seconds or less.

Pressure Measurements - In tests of live ordnance, pressure measurements should be taken to aid in determining the severity of any explosive reaction(s) which occurs.

C-3 UNCLASSIFIED



## UNCLASSIFIED

Security Classification								
DOCUMENT CONTROL DATA - R & D								
:Svewis, classification of little, body of abaltaci and indexing amoutation time to be to 1. ORIC'NATING ACTIVITY (Corporate author)		26. REFORT SECURITY CLASSIFICATION						
	Unclassified							
Naval Ordnance Laboratory								
White Oak, Maryland 20910	DOCUMENT CONTROL DATA - R & D  Indication and of the content and	N/A						
DEVELOPMENT AND TEST OF THERMAL PROTECTION METHODS FOR BOMB FUZES TO EXTEND COOK-OFF TIME IN LARGE AIRCRAFT FUEL FIRES								
4. DESCRIPTIVE NOTES (Type of report and inclusive pates)								
t- ku: HORIS) (First name, middle initie), lest name)								
DONALD LEVINE								
8 REPORT DATE	78. TOTAL NO O	F PAGES	16. NO OF HEFS					
9 December 1971	1							
FA. CONTRACT OR GRANT NO	SE ORIGINATOR	S REPORT NUM	BE #(\$)					
b. PROJECT NO. Task NOL-346/NMC	NOLTR 71-124							
¢.	98. GTHER REPO	AT NOIN (Any of	ther numbers that may be easigned					
d	into youth)							
Evaluation; date statement applied 10/22/71. Other requests for this publication must be referred to NOL, Code 233.								
11. SUPPLEMENTARY NOTES	12 SPONSORING	MILITARY ACTI	VITY					
			Command					
13 ABSTRACT	Washing	con, D.C.	. 3					
(U) Both experimental and theoretical investigations have been performed on ways of extending the cook-off times of the Nose Fuze M904E2 and M148 Adapter Booster when engulfed in a liquid hydrocarbon fire. Several insulative materials were examined for utilization in fuzes and adapter booster fixes. The materials showing the greatest promise when fabricated into sleeves were Candidates No. 10 and No. 14. These materials extended the cook-off times of the Fuze M904E2 with deflagration being the usual reaction. An open Adapter Booster problem was determined to exist. When the Adapter Booster was unprotected and flame was directed into the open cavity, cook-off resulted in approximately four minutes. When the Adapter Booster was protected with intumescent paint on the adapter ring, and a disc and washer of Candidate No. 10 was inserted into the booster cavity, times in excess of 12 minutes were obtained. When the two fixes were combined the times to cook-off, with a somewhat lower fire temperature, were in excess of 12 minutes with detonation being the reaction. This report describes the cook-off test procedures and discusses the laboratory and field results of cook-off fixes for Fuze M904E2 and M148 Adapter Booster.								
Pro.								

DD FORM 1473 S/N 0101-807-6801 (PAGE 1)

UNCLASSIFIED
Security Classification

UNCLASSIFIED

Pire tests Puze cook-off Intumescent paint Thermo insulation	Security Classification		Lini	LINK A		LINK .		LINK C	
Pire tosts Puze cook-off Intumescent paint Thermo insulation		民主》 安心我们是	ROLE	* 1	ROLE	# Y	HOLE	wT	
Puze cook-off Intumescent paint Thermo insulation									
Puze cook-off Intumescent paint Thermo insulation	Fire tests								
Chermo insulation									
Thermo insulation	ruze cook-o	ff							
Thermo insulation	Totumescent	paint							
					Ì				
	Thermo insulation								
			1						
			1						
			vicios in the second						
			-						
	et a		1						
				1					
	<u>, 4.</u>						1		
	*								
		·							
			the sign of						
								•	
			1						

DD PORM 1473 (BACK) (PAGE: 2)

UNCLASSIFIED
Security Classification